

~~SENSITIVE SECURITY INFORMATION~~

Tri-County Metropolitan Transit District

May 14, 2014

If this document/information is found, please deliver to appropriate department or position as soon as possible.

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
3394705	2641	A			ME3	T1 MECH COUPLER HTR PT2 12/07	222000	CCTV EQUIPMENT			7.00	06/20/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
3424241	2641	A			ME0	T1 ELEC. HEAD CONTACT AD 10/07	222000	CCTV EQUIPMENT			7.00	06/21/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
		B			ME0	T1 ELEC. HEAD CONTACT AD 10/07	222000	CCTV EQUIPMENT			7.00	06/22/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		C			ME0	T1 ELEC. HEAD CONTACT AD 10/07	222000	CCTV EQUIPMENT			7.00	06/27/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
3951554	3909	A			F20	T4 CCTV DVR LCD INSTALL 9/10	4LV	CCTV EQUIPMENT			3.00	01/17/2014	STARTED LCD INSTALL HAD TO	CUSTOM MOUNT ALSO COULD NOT FIND PROPER CABLE TO FINISH INSTALL-NO PARTS IN STORES	81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
4163155	3806	A			S51	UNSCHEDULED SYSTEM INSPECTION	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB ARTIC AREA)	0.50	02/08/2012	CHECK CAM #3 AIM ITS CORRECT		86	SUSPECTED FAILURE	CK	CHECKED	R1
		B			S51	UNSCHEDULED SYSTEM INSPECTION	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB)	1.00	02/08/2012	CHECK CAM #4		78	OUT OF SPECIFICATION	AJ	ADJUSTED	
4163336	3756	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.25	02/08/2012	WORKING NORMAL NO DEFECT		81	SCHEDULED CHANGE/INSTALLATION	IN	INSPECTED	R1
4168300	3522	A			N99	DEFERRED PM ITEMS 9/2001	222000	CCTV EQUIPMENT		COUPLER UNIT ('A' CAR)	1.00	01/31/2012	PM INSP. 313		81	SCHEDULED CHANGE/INSTALLATION	IN	INSPECTED	R1
4188690	3607	C			S09	COUPLER FAILURE	2LV	CCTV EQUIPMENT			0.50	10/05/2012	TEST A COUPLER, REARVIEW CCTV				TT	TESTED	R1
4203617	3721	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	01/04/2012					IN	INSPECTED	R1
	3801	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/04/2012					IN	INSPECTED	R1
4204662	3395	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	01/09/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/09/2012					IN	INSPECTED	
4206363	3721	C			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/05/2012					IN	INSPECTED	R1
		E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/05/2012					IN	INSPECTED	
4206960	3607	B			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.50	01/23/2012					IN	INSPECTED	R1
		E			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/23/2012					IN	INSPECTED	
4206961	3661	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	01/04/2012					IN	INSPECTED	R1
		E			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/04/2012					IN	INSPECTED	
4210379	3419	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			1.00	01/04/2012	T/S RT. MONITORS DARK FOUND	BAD CONTROL	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4210750	3632	L			N00	T-1 PM 4,500 MILE PKG	222460	WIRING/CONNECTIONS		'A' CAR	1.00	01/09/2012	REPAIR BAD CONNECTOR @ VDA		35	ELECTRICAL FAILURE	RE	REPAIRED	R1
4211304	3632	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/23/2012					IN	INSPECTED	R1
	3669	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.25	01/23/2012					IN	INSPECTED	R1
4211308	3735	A			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	01/12/2012					IN	INSPECTED	R1
	4163	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	01/13/2012					IN	INSPECTED	R1
		D			N32	T-4 PM 40,500 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB ARTIC AREA)	1.00	01/13/2012	ADJUST FOCUS ON CAMERA #2		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	
	4185	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	01/13/2012					IN	INSPECTED	R1
		B			N32	T-4 PM 40,500 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB ARTIC AREA)	1.00	01/13/2012	ADJUST FOCUS ON CAMERA #2		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	
4211967	4096	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT			1.50	01/05/2012	TEST-NDF		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4213769	4159	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/30/2012					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4213770	1209	B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			2.00	01/30/2012					IN	INSPECTED	
		F			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	01/30/2012					IN	INSPECTED	R1
4214314	1209	C			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/30/2012					IN	INSPECTED	
		G			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	02/07/2012					IN	INSPECTED	R1
					N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/07/2012					IN	INSPECTED	
4214540	3913	B			S16	PROPULSION FAILURE	222100	CAMERA		CCTV CAMERA (A-CAB)	1.50	01/12/2012	TESTED A END CCTV CAMERA	POSSIBLE DARK TEST,NDF	86	SUSPECTED FAILURE	TT	TESTED	R1
4215688	3726	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS			1.00	01/13/2012	T/S LEFT MONITOR SHOWING RIGHT	SIDE VIEW COAX CABLES ON VDA WERE SWAPPED GOING TO CONTROL BOX.	67	MISWIRED	RQ	REWIRE/REINSULATED	R1
	4095	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS			1.00	01/13/2012	T/S LEFT MONITOR SHOWING RIGHT	SIDE VIEW COAX CABLES ON VDA WERE SWAPPED GOING TO CONTROL BOX.	67	MISWIRED	RQ	REWIRE/REINSULATED	R1
4215740	3750	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/09/2012					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/09/2012					IN	INSPECTED	
4216010	3410	A			S99	DEFERRED DEFECT FAILURES 9/01	4LV	CCTV EQUIPMENT			2.00	04/08/2012	T/S ATTEMPTED MONITORS		27	DEFECTIVE	TS	TROUBLESHOOT	R1
4216379	3910	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.50	01/24/2012					IN	INSPECTED	R1
	4157	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/25/2012					IN	INSPECTED	R1
4217232	3850	A			S51	UNSCHEDULED SYSTEM INSPECTION	4LVFE1	MOUNT/HOUSING/MIRROR			1.00	01/17/2012	CHECKED-NDF				IN	INSPECTED	R1
4218058	331	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	01/30/2012					IN	INSPECTED	R1
4218062	3395	G			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR			0.50	01/25/2012	REMOVE WATER/TIGHTEN SCREWS		53	LEAKING/CONDENSATION	TI	TIGHTENED	R1
4219404	3630	A			S08	CARBODY/CAR/CAB INTER FAILURE	2LVA1	CAMERA HOUSING		CCTV CAMERA (B-CAB ARTIC AREA)	2.50	01/21/2012	T/S WHY WATER INTRUSION IN	INTERIOR CAMERAS DISCOVERED H2O LEAKING INTO EVAPORATOR ON B-HVAC FOUND LEAK & SEALED	53	LEAKING/CONDENSATION	TS	TROUBLESHOOT	R1
4219436	1209	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFE	CAMERA			0.50	01/22/2012	CLEANED EXT CAMERA & INSPECTED	OK.	31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
	3726	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB)	1.00	01/20/2012	FROM 219,125 B CAMERAS ARE	FUZZY ON THE REAR SPLIT SCREEN UNCOUPLED & CLEANED ELEC HEAD NO HELP BOTH SIDES AFFECTED WHILE CLEANING OBSERVED T-1 COUPLER AT LEAST 1 INCH BELOW T-2 COUPLER, COULD BE WORKING WHILE TRAVELING	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	4159	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB)	1.00	01/20/2012	FROM 219,125 B CAMERAS ARE	FUZZY ON THE REAR SPLIT SCREEN UNCOUPLED & CLEANED ELEC HEAD NO HELP BOTH SIDES AFFECTED WHILE CLEANING OBSERVED T-1 COUPLER AT LEAST 1 INCH BELOW T-2 COUPLER, COULD BE WORKING WHILE TRAVELING	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4219490	4159	B			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/04/2012					IN	INSPECTED	R1
		F			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/04/2012					IN	INSPECTED	
4219680	4096	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT		'A' CAR	6.50	01/22/2012	LOOSE CONNECTION OVERHEAD LT	REAR VIEW REPLACE APPARTUS RACK COMPONENT-LOOSE WIRE CONNECTION. MAYBE BAD	63	MECHANICAL FAILURE	TS	TROUBLESHOOT	R1
4219687	4154	B			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS		'A' CAR	1.00	01/21/2012	FOUND LOOSE/POOR COAXLE CON-	NECTION ON A APP CRACK SECURED CABLE AND	57	LOOSE	SC	SECURED	R1
4219895	3661	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			1.25	01/24/2012	T/S CAMERA #3, USED LAPTOP TO	DVR AND NO CAMERA-3 TOOK H.D. UPSTAIRS WONT OPEN FILES CHECK CONNECTIONS AT CAMERA, OK DVR MAY NEED R/R	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
	3801	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.50	01/22/2012	T/S CODE 7069,FOUND CAMERA#3	ERROR NEEDS MORE T/S.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB ARTIC AREA)	7.50	01/24/2012	T/S CAMERA #3 NOT WORKING,RING	OUT COAX CABLE,FOUND OPEN CIRCUIT FROM CAMERA #3 TO REC-ORDER UNIT TRACE COAX CABLE ONROOFTOP FOUND X48J TO X48P NOTPUSHED IN ALL THE WAY,PUSH PLUG-IN AND TESTED CAMERA#3 RECORDING,CHECK DATA PACK FOR IMAGE.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	
	3806	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			3.50	01/24/2012	T/S CAM#3 ERROR SWAPPED REC.	& CAMS NO CHANGE CAM#3 HAS 12VDC SWAPPED CABLES @ REC. ERROR FOLLOWED	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		C			S23	CCTV/APC/EVENT RECORDER FAILS	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB ARTIC AREA)	1.00	01/24/2012	R/R CAM'S		86	SUSPECTED FAILURE	RR	REMOVED AND REPLACED	
4221231	3756	A			S51	UNSCHEDULED SYSTEM INSPECTION	4LV	CCTV EQUIPMENT			0.25	02/08/2012	SCREEN DISPLAY LOOKS NORMAL		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4222578	4096	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT		'A' CAR	1.50	01/27/2012	CHECK OUT ALL CAMERA-NDF		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4223192	4096	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT			1.00	01/28/2012	ADJ. MONITOR SETTING FOR	BETTER VIEW	65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4223217	3661	G			N02	T-1 PM 13,500 MILE PKG	222100	CAMERA		CCTV CAMERA (A-CAB)	1.50	02/02/2012	R/R CAMERA 1 NO SIGNAL				RR	REMOVED AND REPLACED	R1
4223447	4159	E			N30	T-4 PM 9,000 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB)	0.25	02/04/2012	ADJUSTED CAMERA #1		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4223657	4159	A			N30	T-4 PM 9,000 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB)	0.50	01/30/2012	ADJUSTED CAMERA #1 TO SPEC		78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1
		B			N30	T-4 PM 9,000 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB ARTIC AREA)	0.50	01/30/2012	ADJUSTED CAMERA #2 TO SPEC		78	OUT OF SPECIFICATION	AJ	ADJUSTED	
4224300	3687	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.75	01/30/2012	T/S CCTV-MONITORS BLINK TO BLK	SCREEN WHEN DOORS OPEN TO CLOSE FOR A MOMENT,UNKNOWN REASON NOT REPAIRED	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4227161	3750	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	02/11/2012					IN	INSPECTED	R1
4227167	3921	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	02/12/2012					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.25	02/12/2012					IN	INSPECTED	
4227834	3687	A			S10	COMMUNICATION FAILURE	4LVFE	CAMERA, EXTERIOR			0.50	02/02/2012	T/S CAMERA-CLEANED LENSE COVER	& TEST.	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4228478	3756	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/19/2012					IN	INSPECTED	R1
	3909	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.10	02/16/2012					IN	INSPECTED	R1
4228608	3921	A			S08	CARBODY/CAR/CAB INTER FAILURE	2LVFG	MOUNTS/HARDWARE			0.50	02/04/2012	TIGHTENED SWIVEL MOUNT		57	LOOSE	TI	TIGHTENED	R1
4228631	3750	B			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS			1.00	02/05/2012	R/R WIRING CONNECTORS		05	BROKEN	RR	REMOVED AND REPLACED	R1
4228861	3669	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/19/2012					IN	INSPECTED	R1
	3726	E			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	02/18/2012					IN	INSPECTED	R1
	4120	A			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/18/2012					IN	INSPECTED	R1
4229393	4159	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/02/2012					IN	INSPECTED	R1
4231149	3519	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	02/12/2012					IN	INSPECTED	R1
4231983	3721	G			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			1.00	02/19/2012	T/S B-LEFT MONITOR NO WORKING	BAD C BOX.	35	ELECTRICAL FAILURE	TS	TROUBLESHOOT	R1
4231986	3749	H			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR			1.00	02/22/2012	R/R RT REARVIEW CAMERA WINDOW	EXT.	31	DIRTY	RR	REMOVED AND REPLACED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4232498	4120	A			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR			1.00	02/22/2012	R/R LFT REARVIEW CAMERA WINDOW	EXT	31	DIRTY	RR	REMOVED AND REPLACED	
					S52	CCTV DATA PACK/EVENT RECORDER	4LVFE	CAMERA, EXTERIOR			0.75	02/13/2012	VIEWED MONITOR,IMAGE SLIGHTLY	GRAINY,BUT IMAGE DETAILS VISIBLE REMOVED CCTV COVER LOOKA AT WIRING OF CAMERA UNITFOR REAR IMAGE CLEANED GLASS WINDOW NO SIGNIFICANT CHANGES LOOKED AT WIRING ON BACK OF MONITOR IT WAS CONNECTED.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4235202	3735	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			1.25	03/21/2012	TEST B-CAB MONITOR RIGHT SIDE	COUPLING TO ANOTHER TRAIN,ALL MONITORS WORK PROPERLY	86	SUSPECTED FAILURE	TT	TESTED	R1
4234677	3700	B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/28/2012					IN	INSPECTED	R1
		E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/29/2012					IN	INSPECTED	
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/29/2012					IN	INSPECTED	
4235010	3449	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT			0.25	03/28/2012	NOT BLANK NOW.				IN	INSPECTED	R1
4235590	4147	B			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.75	02/20/2012	TEST SYSTEM TO VERIFY FIX,	FOUND'A'END RIGHT SIDE MONITORBAD	86	SUSPECTED FAILURE	TT	TESTED	R1
		E			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.50	02/20/2012	CLEANED LENS COVERS ON CAMERAS		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	
4235622	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	4LV	CCTV EQUIPMENT			1.00	02/20/2012	T/S DARK MONITOR, WAS AUXED OFF	ON ARRIVAL_AUXED ON,CHECKED 412 OK,DHECK 407,OK,NEEDS TO BE ADJUSTED IN DAYLIGHT WHEN CAMERA ISN'T FACING AN OVER-HEAD LIGHT GOOD FOR SERVICE.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4235657	4154	H			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT		'B' CAR	0.50	02/23/2012	REPLACE MISSING VISORS'B'CAB		66	MISSING	RL	REPLACED	R1
4236279	3449	C			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/03/2012					IN	INSPECTED	R1
	4159	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/02/2012					IN	INSPECTED	R1
4237478	3340	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	03/03/2012					IN	INSPECTED	R1
	3633	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/03/2012					IN	INSPECTED	R1
4237479	2881	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/03/2012					IN	INSPECTED	R1
	3741	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	03/04/2012					IN	INSPECTED	R1
4238441	2641	A			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/10/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
		B			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/13/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		C			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/14/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		D			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/16/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		E			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/20/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		F			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/21/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		G			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/24/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		H			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/28/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		I			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			5.00	03/29/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		J			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			7.00	03/30/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
	3340	A			MD6	T1 SIDE VIEW CCTV 8/07	222000	CCTV EQUIPMENT			2.00	02/27/2012	CCTV MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
4238578	3924	A			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT			2.00	03/19/2012	CAB CAM MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
		B			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT			6.75	04/03/2012	CAB CAM MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		C			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT			2.00	04/10/2012	CAB CAM MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		D			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT			3.00	04/20/2012	CAB CAM MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
4240469	3801	A			S53	CAR MOVES	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	0.50	03/01/2012	INSPECTED CAMERA #2 FOR GOOD	IMAGE. TESTED OK.	86	SUSPECTED FAILURE	IN	INSPECTED	R1
4240481	908	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			2.00	03/01/2012	I HAD TO DRILL OUT THE TAMPER	PROOF SCREW ON CAMERA #4, NEEDS REPLACED. I THINK DEFECTIS ON THE ROOF. BOTH CAMERA #3,4 LOOK FINE AT CAMERA BUT BAD SIGNAL AT RECORDER.			TS	TROUBLESHOOT	R1
	3700	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			7.00	03/01/2012	T/S CAMERA 3,4 NO VIDEO. R/R	NEW ROAD RECORDER, NO HELP. FOUND WIRE #87122.14 ON TER- MINAL STRIP BROKEN AT SPADE, RECRIMPED WITH NEW ONE. TRIED NEW CAMERA #4 POSITION. DIDN'THELP. ASSUME MUST BE CONNEC- TION SOMEWHERE ON ROOF. NEEDS FURTHER T/S.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	3801	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			3.00	02/29/2012	TS CAMERA #2 FOR NO IMAGE AND	CAMERA #4 FOR OUT OF FOCUS. USE PORABLE MONITOR. FOUND ALLCAMERAS HAD GOOD IMAGE, BUT CABLES AT BACK OF RECORDER ON CAMERAS #2,3,4 HAD NO IMAGE. CABLE END ON CAMERA #2,4 HAD BAD ENDS. R/R CABLE ENDS ON CAMERA #2,4, CAMERA #1,2 HAD GOOD IMAGE, BUT CAMERA #3,4 STILL DIDNT HAVE IMAGE. NEED MORE T/S.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			7.50	03/01/2012	T/S CAMERA #3,4 FOR NO VIDEO	RING OUT COAX 3,4 FROM CAMERASTO RECORDER. FOUND COAX #4 WITH OPEN CIRCUIT & COAX #3 WITH INTERMITTENT OPEN CIRCUITTRACE BOTH CIRCUIT TO BAD COAXENDS AT X205-112 PLUG R/R COAX ENDS ON BOTH CABLES. TESTBOTH SIGNALS ON COAX #3,4. OK ALSO R/R ZERK NUT ON CAMERA HOUSING #4. CK DATA PACK FOR GOOD IMAGE AFTER REPAIR, LOOKSOK.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	
4242489	6501	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/10/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/10/2012					IN	INSPECTED	
4243686	3850	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/09/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/09/2012					IN	INSPECTED	
4244403	1209	L			N13	T-2 PM 27,000 MILE PKG	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	0.20	03/26/2012	CLEANED CAMERA		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4244570	908	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			3.00	03/06/2012	RIGHT SIDE CONTROL BOX FAILED	REPLACE RIGHT SIDE CONTROL BOX	35	ELECTRICAL FAILURE	RR	REMOVED AND REPLACED	R1
4244923	3340	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/11/2012					IN	INSPECTED	R1
	4096	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/10/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/10/2012					IN	INSPECTED	

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4245475	3911	A			S52	CCTV DATA PACK/EVENT RECORDER	4LVFE	CAMERA, EXTERIOR			0.50	03/07/2012	CLEAN EXTERIOR HOUSING WINDOW	& TEST OK.	31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4245610	3631	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	04/11/2012					IN	INSPECTED	R1
4245612	3919	G			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR		'A' CAR	1.50	03/15/2012	FIX CAMERA		15	CONTAMINATED	CL	CLEANED/WASHED/FUMIGATED	R1
4247334	3340	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/17/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/17/2012					IN	INSPECTED	
4247781	3419	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/20/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	03/20/2012					IN	INSPECTED	
4248793	3850	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	1.00	03/12/2012	CAMERA #2 WAS BLACK-				TT	TESTED	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	2.50	03/13/2012	BAD CABLE INSIDE DVR HOUSING				TS	TROUBLESHOOT	
		C			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	1.00	03/14/2012	WORKS WELL				TT	TESTED	
4248795	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			1.00	03/12/2012	T/S CAMERA 3 FUZZY HOOKED UP	PORTABLE MONITOR TO CAMERA-3 IMAGE FINE RECONNECTED TOOK DATA PACK UPSTAIRS/VIEWED IMAGE FOR CAMERA 3 WAS A LITTLE GRAINY-RECONNECTED GOT GOOD IMAGE	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S52	CCTV DATA PACK/EVENT RECORDER	2LVFF	WIRING/CONNECTIONS			1.75	03/12/2012	R/R BNC CONNECTOR CAMERA 3	AT BACK OF DVR	71	OUTPUT IMPROPER	RR	REMOVED AND REPLACED	
		C			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.50	03/12/2012	AFTER R/R THE BNC CONNECTOR	PUTTING EVERYTHING BACK TOGETHER PULLED DATA PACK AND VIEWED IMAGE-MUCH CONSIDERABLY BETTER	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	
4248797	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.00	03/12/2012	CLEANED OFF SNOW/CLEAR VIEW		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4249470	3661	B			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	04/05/2012					IN	INSPECTED	R1
		D			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/05/2012					IN	INSPECTED	
4250216	3831	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	03/22/2012					IN	INSPECTED	R1
	4117	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/24/2012					IN	INSPECTED	R1
4250732	4095	A			S52	CCTV DATA PACK/EVENT RECORDER	4LVFE	CAMERA, EXTERIOR			0.50	03/15/2012	CAMERA LOOKS DRY,CLEANED &	APPLIED RAINEX	69	NO DEFECT FOUND	CL	CLEANED/WASHED/FUMIGATED	R1
4251238	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT		'A' CAR	0.50	03/17/2012	YES, MISSING?		66	MISSING	IN	INSPECTED	R1
4251482	3669	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/10/2012					IN	INSPECTED	R1
	3721	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/10/2012					IN	INSPECTED	R1
4251593	3726	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS			0.50	03/18/2012	SWAPPED CABLES AT RECEIVERS	& TEST			SP	SWAPPED	R1
	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.50	03/18/2012	T/S CCTV PROBLEM,FOUND REAR	IMAGES IN 225 CROSSED IN'A' CAB,FOUND RECEIVERS COAX CABLES SWAPPED	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS			0.50	03/18/2012	SWAPPED CABLES AT RECEIVERS-OK		67	MISWIRED	SP	SWAPPED	
4251673	3631	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/27/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	03/27/2012					IN	INSPECTED	
4252106	1209	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.50	03/19/2012	TESTED REAR VIEW LOOSE CABLE	TIGHTENED-OK	86	SUSPECTED FAILURE	TT	TESTED	R1
4252221	4159	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/27/2012					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
		E			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.25	03/27/2012					IN	INSPECTED	
4252226	3449	G			N30	T-4 PM 9,000 MILE PKG	4LVFE1	MOUNT/HOUSING/MIRROR			1.00	03/22/2012	R/R L CAMERA TOP COVER FOR	BAD LENS DISTORTION/IMAGE	82	SCRATCHED	RR	REMOVED AND REPLACED	R1
4253125	6501	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/11/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/11/2012					IN	INSPECTED	
4254409	4120	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/26/2012					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	04/26/2012					IN	INSPECTED	
4254437	3806	A			S51	UNSCHEДУLED SYSTEM INSPECTION	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB ARTIC AREA)	0.25	03/26/2012	T/S CAMERA AIMING,L.T NOT WORK	ING,PULLED DP.	78	OUT OF SPECIFICATION	TS	TROUBLESHOOT	R1
		B			S51	UNSCHEДУLED SYSTEM INSPECTION	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB)	0.25	03/26/2012	ADJ CAM.		78	OUT OF SPECIFICATION	AJ	ADJUSTED	
		C			S51	UNSCHEДУLED SYSTEM INSPECTION	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB ARTIC AREA)	0.25	03/26/2012	ADJ CAM.		78	OUT OF SPECIFICATION	AJ	ADJUSTED	
		D			S51	UNSCHEДУLED SYSTEM INSPECTION	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB ARTIC AREA)	0.25	03/26/2012	ADJ CAM.		78	OUT OF SPECIFICATION	AJ	ADJUSTED	
		E			S51	UNSCHEДУLED SYSTEM INSPECTION	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB)	0.25	03/26/2012	ADJ CAM.		78	OUT OF SPECIFICATION	AJ	ADJUSTED	
4254714	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE1	MOUNT/HOUSING/MIRROR			0.75	03/24/2012	CHECKED AND CLEANED BOTH RT/LT	SIDE HOUSINGS	31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4254755	4154	B			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	04/27/2012					IN	INSPECTED	R1
4254758	3394	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/06/2012					IN	INSPECTED	R1
4255581	3633	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/08/2012					IN	INSPECTED	R1
		3741	F		N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	04/08/2012					IN	INSPECTED	R1
4256963	3632	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	04/04/2012					IN	INSPECTED	R1
4256971	4157	E			N30	T-4 PM 9,000 MILE PKG	4LVFE	CAMERA, EXTERIOR			2.00	04/05/2012	INSTALL 4MM NUT SERTS IN	HOUSING			RE	REPAIRED	R1
4257945	3522	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.80	04/03/2012					IN	INSPECTED	R1
		3789	F		N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/04/2012					IN	INSPECTED	R1
4260098	3783	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/06/2012					IN	INSPECTED	R1
		3850	F		N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/07/2012					IN	INSPECTED	R1
4260119	3831	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/25/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/25/2012					IN	INSPECTED	
4260357	3632	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/11/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/11/2012					IN	INSPECTED	
4260806	1209	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.50	04/09/2012					IN	INSPECTED	R1
4260826	3401	A			S52	CCTV DATA PACK/EVENT RECORDER	4LV	CCTV EQUIPMENT			1.50	04/03/2012	REPLACE THE PROTOTYPE CCTV/DVR		81	SCHEDULED CHANGE/INSTALLATION	RR	REMOVED AND REPLACED	R1
4261444	4154	D			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	04/21/2012					IN	INSPECTED	R1
4261835	3783	A			S23	CCTV/APC/EVENT RECORDER FAILS	22450	CAMERA			1.00	04/04/2012	CLEANED/DRIED, GOOD TO GO				CL	CLEANED/WASHED/FUMIGATED	R1
4261961	3394	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/17/2012					IN	INSPECTED	R1
		3419	F		N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/17/2012					IN	INSPECTED	R1
4262184	3632	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT			5.50	04/05/2012	REMOVE DATAPACK & VIEWED FOR	MISSING IMAGE ALL IMAGES PRESENT BUT CAM 3 BAD PICTURE	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
		B			S10	COMMUNICATION FAILURE	2LVA	CAMERA		CCTV CAMERA (B-CAB)	1.00	04/05/2012	R/R CAMERA & POSITION 4(3/4)	SWAPPED AT DVR/TEST GOOD AT CAMERA BUT NO PICTURES TO DVR (CHECK WIRING TO DVR(COAX)) FOUND CAM 3/4 COAX WIRES REVERSED PUT WIRES BACK WHERE THEY BELONG RE-TESTED,SEEMS OK NOW	27	DEFECTIVE	RR	REMOVED AND REPLACED	
	3661	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT			2.50	04/05/2012	CHECK FOR ERROR CODE 7069	CHECK HEALTH RELAY FOR OP OK FOUND LCD UNPLUGGED AT BACK OF DOOR LCD SHOWS CAM 3PROBLEMSWAPPED COAX FROM 3 TO 1 AND THEN THE READ OUT SAID CAM 1 PROBLEM CAMERA 3 HAS THE AS THE PROBLEM NEED TO PULL BACK AND CHECK WHICH CAM IMAGE IS MISSING			TS	TROUBLESHOOT	R1
	3735	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT			1.00	04/05/2012	T/S CHECKING CAMERA-3 AT CAM.	THEN WENT TO ROAD RECORDER & CHECKED ALL CAMERAS FROM CAR TO RECORDER CHECKED OK			TS	TROUBLESHOOT	R1
	4185	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT			4.00	04/05/2012	REVIEWED DATA PACK FOUND IMAGE	UNSTABLE & VIEW MUCH DIFFERENT THEN THE OTHER END,NOTICE CAM 3/4 WOULD GO DARK AS THE TRAINWENT AROUND CORNERS,BROUGHT INTO SHOP FOUND IN THE B-END JUNCTION BOX JUST BEFORE ARTICA-BAD CONNECTION @ THE COAX TIGHTENED COLLAR UP AROUND SHIELDING/PROBLEM GONE	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S10	COMMUNICATION FAILURE	2LVA	CAMERA		CCTV CAMERA (B-CAB)	1.00	04/05/2012	REINSTALLED ORIGINAL CAMERA-4	OK,SHOULD CHECK	86	SUSPECTED FAILURE	RR	REMOVED AND REPLACED	
4262425	4156	B			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	04/18/2012					IN	INSPECTED	R1
4262427	3783	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/19/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/19/2012					IN	INSPECTED	
4262910	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT		'B' CAR	1.00	04/06/2012	LEFT-REAR VIEW WHITE & HAZY	TRIED COUPLER CLEAN. CKING CONNECTIONS, ETC. NOTE: OTHER END OF CONSIST #232 RT REAR VIEW SHOWS 1/2 VIEW & FUZZY. TOP TRIED TO GET DOOR/PANEL OPEN ON 103 BUT COULD NOT OPENPANEL FOR BETTER ACCESS.	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4262965	4185	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE1	MOUNT/HOUSING/MIRROR			0.50	04/06/2012	T/S SMUDGE ON CAMERA-CHECK THE	CAMERA VIEW AGAINST THE OTHER 3 VIEWS-NO DIFFERENCE NOTED, LOOKS FAIRLY CLEAR IN YARD.	31	DIRTY	TS	TROUBLESHOOT	R1
4262982	3783	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	04/16/2012					IN	INSPECTED	R1
4262983	3924	D			N00	T-1 PM 4,500 MILE PKG	222470	MOUNTS/HARDWARE			0.25	04/14/2012	R/R BROKEN STAND OFF CONTROL	BOXES	05	BROKEN	RR	REMOVED AND REPLACED	R1
4264312	3919	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.50	05/11/2012					IN	INSPECTED	R1
4264317	3401	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.80	04/22/2012					IN	INSPECTED	R1
	4096	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/23/2012					IN	INSPECTED	R1
4264322	4159	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	05/22/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/22/2012					IN	INSPECTED	
4264323	4120	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/11/2012					IN	INSPECTED	R1
		B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/11/2012					IN	INSPECTED	
4264330	3340	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/27/2012					IN	INSPECTED	R1
	3741	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	05/23/2012					IN	INSPECTED	R1
4266021	3661	C			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/11/2012					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4266028	3419	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/11/2012					IN	INSPECTED	
	3797	D			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/09/2012					IN	INSPECTED	R1
4266588	3632	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/09/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/18/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/18/2012					IN	INSPECTED	
4266590	3790	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	04/19/2012					IN	INSPECTED	R1
	3850	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/18/2012					IN	INSPECTED	R1
4267685	3661	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	05/14/2012					IN	INSPECTED	R1
	4147	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	05/15/2012					IN	INSPECTED	R1
4268850	3215	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/07/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/07/2012					IN	INSPECTED	
4269722	3721	A			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/29/2012					IN	INSPECTED	R1
	3726	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.70	05/27/2012					IN	INSPECTED	R1
4270302	3395	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/22/2012					IN	INSPECTED	R1
	3419	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/23/2012					IN	INSPECTED	R1
4270303	3700	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/26/2012					IN	INSPECTED	R1
	4159	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	05/27/2012					IN	INSPECTED	R1
4270310	4120	A			N22	T-3 PM 13,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (B-CAB ARTIC AREA)	0.75	05/11/2012	T/S B-END CAMERA		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4270909	3924	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/08/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	05/08/2012					IN	INSPECTED	
4270911	3783	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/11/2012					IN	INSPECTED	R1
	3850	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/09/2012					IN	INSPECTED	R1
4271484	3783	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LV	CCTV EQUIPMENT			1.00	04/24/2012	INSP CAMERA-CLEANED ELEC HEAD	ALL GOOD.	61	MALFUNCTION/REASON UNKNOWN	IN	INSPECTED	R1
4271551	4147	B			N10	T-2 PM 4,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (B-CAB)	0.50	04/30/2012	R/R CORRODED CAMERA B'LEFT	FOUND HEATER FOR CAMERA UNPLUGGED, AND SILICA PACK MISSING	16	CORRODED	RR	REMOVED AND REPLACED	R1
4271554	3919	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/26/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/26/2012					IN	INSPECTED	
4271556	3721	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	05/24/2012					IN	INSPECTED	R1
	4120	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	05/25/2012					IN	INSPECTED	R1
4271988	4157	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVA	CAMERA		CCTV CAMERA (A-CAB)	0.50	04/25/2012	CHECKED CAMERA AIM, IT IS AS IT	SHOULD BE	86	SUSPECTED FAILURE	CK	CHECKED	R1
4273020	3735	H			N10	T-2 PM 4,500 MILE PKG	2LVA1	CAMERA HOUSING		CCTV CAMERA (A-CAB)	1.00	05/04/2012	R/R SIDE VIEW CCTV LENS		05	BROKEN	RR	REMOVED AND REPLACED	R1
4273029	3785	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/22/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	05/22/2012					IN	INSPECTED	
4273031	3394	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/02/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	05/02/2012					IN	INSPECTED	
4273419	3633	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/15/2012					IN	INSPECTED	R1
4276143	3721	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/30/2012					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
	4159	B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/29/2012					IN	INSPECTED	R1
4276792	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.50	05/01/2012	T/S REAR VIEW MONITORS DIST-	ORTED-REAR IMAGES ARE BAD DUE TO REAR CAR NOT BEING A CAMERACAR,BECAUSE E-HEAD HAS BEEN MODIFIED ON THE TRAILING CAR IT WILL GO SPLIT SCREEN,	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4276912	3661	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	06/05/2012					IN	INSPECTED	R1
		B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	06/05/2012					IN	INSPECTED	
4276914	3340	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	06/13/2012					IN	INSPECTED	R1
	3921	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	06/12/2012					IN	INSPECTED	R1
4278119	3449	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	06/07/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	06/07/2012					IN	INSPECTED	
4278595	3395	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	06/08/2012					IN	INSPECTED	R1
	3783	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	06/08/2012					IN	INSPECTED	R1
4278601	3631	A			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.40	06/05/2012					IN	INSPECTED	R1
	3669	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.25	06/04/2012					IN	INSPECTED	R1
4278973	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.50	05/06/2012	T/S B-MONITORD DARK,FOUND TAG	OVER BREAKER STATING LEAVE BREAKER OPEN,PER TOM HANSON.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4279084	3394	J			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV			0.75	06/30/2012					IN	INSPECTED	R1
4279631	4096	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.80	06/10/2012					IN	INSPECTED	R1
4281261	3419	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/29/2012					IN	INSPECTED	R1
	3595	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/30/2012					IN	INSPECTED	R1
4281263	3394	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/16/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/16/2012					IN	INSPECTED	
4281264	4157	A			N10	T-2 PM 4,500 MILE PKG	2LVFE	CAMERA			1.00	05/20/2012	CLEANED COVER & HAD BAD COAX	CONNECTION			CL	CLEANED/WASHED/FUMIGATED	R1
4281897	3850	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/28/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/28/2012					IN	INSPECTED	
4282769	4157	C			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	06/13/2012					IN	INSPECTED	R1
		E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	06/13/2012					IN	INSPECTED	
4283340	3721	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	06/07/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	06/07/2012					IN	INSPECTED	
4283951	3340	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	06/07/2012					IN	INSPECTED	R1
	3781	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	06/03/2012					IN	INSPECTED	R1
4284594	1209	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	06/10/2012					IN	INSPECTED	R1
	3721	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	06/11/2012					IN	INSPECTED	R1
4284595	3340	G			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			2.00	05/25/2012	T/S MONITORS SIDE VIEW				TS	TROUBLESHOOT	R1
4284598	3721	A			N20	T-3 PM 4,500 MILE PKG	2LVA1	CAMERA HOUSING		CCTV CAMERA (A-CAB)	1.00	05/29/2012	CLEANED LENS		61	MALFUNCTION/REASON UNKNOWN	CL	CLEANED/WASHED/FUMIGATED	R1
		B			N20	T-3 PM 4,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (B-CAB)	1.00	05/29/2012	CLEANED LENS		61	MALFUNCTION/REASON UNKNOWN	CL	CLEANED/WASHED/FUMIGATED	
4285740	3394	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/22/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/22/2012					IN	INSPECTED	
4286455	3607	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVA	CAMERA		CCTV CAMERA (B-CAB)	1.00	05/21/2012	VIEWED DATA PACKS ALL CAMERAS	WORKING NORMALLY AT THIS TIME	86	SUSPECTED FAILURE	TT	TESTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4287046	4157	A			S08	CARBODY/CAR/CAB INTER FAILURE	222000	CCTV EQUIPMENT	.	.	1.00	05/22/2012	T/S NOISE NEAR B-CAR FOUND	COMING FROM DVR VIA POWER SUPPLY	70	NOISY	TS	TROUBLESHOOT	R1
4287188	3721	G			N20	T-3 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR	.	.	0.50	05/31/2012	REPLACED MISSING VISOR		66	MISSING	IO	INSTALLED ONLY	R1
4287765	3632	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	06/29/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	06/29/2012					IN	INSPECTED	R1
4289007	3661	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	06/26/2012					IN	INSPECTED	R1
		C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	06/26/2012					IN	INSPECTED	R1
4289623	2701	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFG	MOUNTS/HARDWARE	.	.	1.00	05/29/2012	R/R BRACKET		05	BROKEN	RR	REMOVED AND REPLACED	R1
4289630	2701	A			S08	CARBODY/CAR/CAB INTER FAILURE	4LVFG	MOUNTS/HARDWARE	.	.	0.50	05/29/2012	SEE RO 42-89623		05	BROKEN	RR	REMOVED AND REPLACED	R1
4289729	4156	C			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	1.00	06/27/2012					IN	INSPECTED	R1
4289739	4096	G			N10	T-2 PM 4,500 MILE PKG	2LVA1	CAMERA HOUSING	.	CCTV CAMERA (A-CAB)	1.50	06/10/2012	OPEN CLEAN SECURE ECT. TIGHTEN		49	INTERMITTENT/FLUCTUATING	TS	TROUBLESHOOT	R1
4293193	4157	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	07/07/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/07/2012					IN	INSPECTED	R1
4293229	3924	A			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT	.	.	2.00	06/21/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
		D			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT	.	.	3.50	06/23/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		E			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT	.	.	1.75	06/24/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		B			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT	.	.	1.75	06/25/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		F			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT	.	.	6.75	06/28/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		C			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT	.	.	3.00	06/29/2012	WORK ON MOD CAB CAM		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
4293307	3781	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	'A' CAR	1.50	06/02/2012	T/S L SIDE MONITOR DARK		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	'A' CAR	1.00	06/02/2012	T/S L SIDE MONITOR DARK		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4293613	3909	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	07/19/2012					IN	INSPECTED	R1
4294195	3721	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	07/09/2012					IN	INSPECTED	R1
		B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/09/2012					IN	INSPECTED	R1
4294199	1209	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	07/07/2012					IN	INSPECTED	R1
	3721	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	07/11/2012					IN	INSPECTED	R1
	3909	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/09/2012					IN	INSPECTED	R1
4295551	3340	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	1.00	06/20/2012					IN	INSPECTED	R1
4295554	3394	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	07/24/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	07/24/2012					IN	INSPECTED	R1
4296075	3632	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	07/17/2012					IN	INSPECTED	R1
	4095	A			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/19/2012					IN	INSPECTED	R1
4296579	3394	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	06/13/2012					IN	INSPECTED	R1
4297535	3909	C			S52	CCTV DATA PACK/EVENT RECORDER	222460	WIRING/CONNECTIONS	.	.	0.50	06/11/2012	R/R CONTROL BOX WIRING		86	SUSPECTED FAILURE	RR	REMOVED AND REPLACED	R1
4297639	3631	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	07/24/2012					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4297641	1209	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	07/06/2012					IN	INSPECTED	R1
	3910	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	07/07/2012					IN	INSPECTED	R1
4298303	3449	J			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV	.	.	1.00	07/16/2012					IN	INSPECTED	R1
	5040	J			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV	.	.	1.00	07/16/2012					IN	INSPECTED	R1
4298822	3632	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	0.50	10/03/2012	BOTH CAMS POINT WHERE THEY ARE	SUSPOSED TO NOW			IN	INSPECTED	R1
4299882	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	1.00	06/15/2012	SUSPECTED MONITOR MALFUNCTION	SEEMS TO BE WORKING	86	SUSPECTED FAILURE	IN	INSPECTED	R1
4299950	3419	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/20/2012					IN	INSPECTED	R1
	3919	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.50	07/20/2012					IN	INSPECTED	R1
4300368	4096	G			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT	.	.	0.50	06/26/2012	TIGHTEN LOOSE MONITOR B END		57	LOOSE	TI	TIGHTENED	R1
4300371	3756	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.25	07/22/2012					IN	INSPECTED	R1
		B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/22/2012					IN	INSPECTED	
4301594	3215	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVA	CAMERA	.	CCTV CAMERA (B-CAB ARTIC AREA)	7.00	06/24/2012	NEW CAMERA FROM ELMO-R/R CAMER	CAMERA OLDER BUT BETTER, CABLE MAYBE BAD, NEEDS MORE T/S	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4302683	4154	A			S23	CCTV/APC/EVENT RECORDER FAILS	222460	WIRING/CONNECTIONS	.	.	2.00	06/21/2012	RECEIVERS MISWIRED SWITCHED	WIRES, NOW SHOWING CORRECT VIEW	67	MISWIRED	SP	SWAPPED	R1
	4156	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	1.00	06/21/2012	HELPED LOOK AT CAMERA ISSUE		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4303473	4157	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT	.	.	1.00	06/23/2012	CHECKED BLUE SCREEN FOUND B-	COAX CONNECTION AT CONTROL BOX	86	SUSPECTED FAILURE	CK	CHECKED	R1
4303557	2636	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	1.00	07/02/2012	T/S CCTV DEFECT. ONLY THING	FOUND LEFT MONITOR AT CAMERA FUZZY, NEED TO BE LOOKED AT	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	3921	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	2.50	07/03/2012	REVIEWED DATA PACK CKD ALL	CONNECTIONS, CLEANED & REASSEMBLED, ADJD BRIGHT/CONTRAST	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4309294	3632	J			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV	.	.	1.00	07/24/2012					IN	INSPECTED	R1
	4095	J			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV	.	.	1.00	07/25/2012					IN	INSPECTED	R1
4310122	3632	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	08/22/2012					IN	INSPECTED	R1
		C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.50	08/22/2012					IN	INSPECTED	
4310842	3394	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	07/13/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	07/13/2012					IN	INSPECTED	
4310843	3394	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	07/06/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	07/06/2012					IN	INSPECTED	
4311003	3449	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	08/16/2012					IN	INSPECTED	R1
	3700	B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	08/18/2012					IN	INSPECTED	R1
4315008	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	1.50	07/13/2012	LOOSE CONNECTION-WORKING		27	DEFECTIVE	TS	TROUBLESHOOT	R1
4315260	4159	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT	.	.	4.00	07/15/2012	HAD POWER TO ALL TERMINAL WIRE	TO MONITOR TRIED MONITOR DIDNT CHANGE TRIED NEW CONTROL BOX DIDNT HELP ALSO LOOKED AT IN-LINE FUSE & ALL LOOKED GOOD NEEDS FURTHER T/S.	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4315995	3756	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	08/26/2012					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	08/26/2012					IN	INSPECTED	
4316541	3910	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	08/06/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	08/06/2012					IN	INSPECTED	

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4317062	4154	A			S52	CCTV DATA PACK/EVENT RECORDER	4LV	CCTV EQUIPMENT	.	.	0.50	07/18/2012	TESTED MONITORS,WORKING NORMAL		86	SUSPECTED FAILURE	TT	TESTED	R1
4317219	3850	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	09/01/2012					IN	INSPECTED	R1
	6501	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	09/01/2012					IN	INSPECTED	R1
4318253	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	'A' CAR	3.80	07/20/2012	T/S VIDEO RECORDING-WORKING		65	MISADJUSTED/MISALIGNED	TS	TROUBLESHOOT	R1
	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	'A' CAR	3.80	07/20/2012	T/S VIDEO RECORDING-WORKING		65	MISADJUSTED/MISALIGNED	TS	TROUBLESHOOT	R1
4318279	3721	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.50	08/30/2012					IN	INSPECTED	R1
	B				N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.50	08/30/2012					IN	INSPECTED	
4318514	3669	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	08/07/2012					IN	INSPECTED	R1
	3909	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	08/06/2012					IN	INSPECTED	R1
4318596	4096	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT	.	'A' CAR	2.80	07/22/2012	T/S LT. REAR VIEW MONITOR/WIRE	CONNECTIONS/COMPONENTS FOUND PROBLEM CORRECTED	63	MECHANICAL FAILURE	TS	TROUBLESHOOT	R1
4318685	3398	A			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.	.	3.00	07/20/2012	PROGRAM MONITORS		27	DEFECTIVE	PG	PROGRAMMED	R2
	B				R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.	.	5.00	07/23/2012	PROGRAM MONITORS		27	DEFECTIVE	PG	PROGRAMMED	
	C				R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.	.	8.00	07/24/2012	PROGRAM DVRS, FORMAT DATA	PACKS	27	DEFECTIVE	PG	PROGRAMMED	
4319781	3633	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	09/16/2012					IN	INSPECTED	R1
4320470	3449	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	09/04/2012					IN	INSPECTED	R1
	F				N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	09/04/2012					IN	INSPECTED	
4321343	3632	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	2.50	08/28/2012					IN	INSPECTED	R1
	B				N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	08/28/2012					IN	INSPECTED	
	3700	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	2.00	08/28/2012					IN	INSPECTED	R1
4321346	3735	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.75	09/03/2012					IN	INSPECTED	R1
	3910	B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	09/01/2012					IN	INSPECTED	R1
	4159	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	09/02/2012					IN	INSPECTED	R1
4321739	3924	C			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	3.50	07/27/2012	T/S RT MONITOR		71	OUTPUT IMPROPER	TS	TROUBLESHOOT	R1
4321907	4096	A			S08	CARBODY/CAR/CAB INTER FAILURE	4LV	CCTV EQUIPMENT	.	'A' CAR	1.50	07/28/2012	BRACKET IS BROKEN, NO PARTS		05	BROKEN	TR	TEMPORARY REPAIR	R1
	B				S08	CARBODY/CAR/CAB INTER FAILURE	4LV	CCTV EQUIPMENT	.	'A' CAR	1.00	07/28/2012	REPLACE BROKEN MONITOR BRACKET		05	BROKEN	RE	REPAIRED	
4322066	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	'A' CAR	0.80	07/28/2012	CHECKED VIEW-BOTH FINE		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4322165	3924	A			MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT	.	.	3.75	08/24/2012	CAB CAM MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
	B				MC3	T1 CAB CAMERA 3/05	222000	CCTV EQUIPMENT	.	.	4.00	09/09/2012	CAB CAM MOD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
4323213	3401	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	08/11/2012					IN	INSPECTED	R1
	3419	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.50	08/10/2012					IN	INSPECTED	R1
4330190	3401	J			N04	T-1 PM 40,500 MILE PKG	MIL312	TEST: CCTV	.	.	0.50	08/12/2012					IN	INSPECTED	R1
4331677	3850	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	08/17/2012					IN	INSPECTED	R1
	G				N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	08/17/2012					IN	INSPECTED	
4331678	3721	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	2.00	09/18/2012					IN	INSPECTED	R1
	4096	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	2.00	09/17/2012					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4331688	3631	A			S51	UNSCHEDULED SYSTEM INSPECTION	4LV	CCTV EQUIPMENT			0.50	09/22/2012	TEST CCTV SYSTEM ALL CAMERAS	LOOK OK.	61	MALFUNCTION/REASON UNKNOWN	TT	TESTED	R1
4333382	3917	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVFE	CAMERA			0.25	08/14/2012	INSPECTED CAMERA,ADJUSTED	CORRECTLY	65	MISADJUSTED/MISALIGNED	IN	INSPECTED	R1
4333489	3831	C			X03	WHEEL TRUING - FOR WEAR	4LVFG	MOUNTS/HARDWARE			1.00	08/16/2012	R/R L4 MONITOR MOUNT		05	BROKEN	RR	REMOVED AND REPLACED	R1
4333526	3444	A			S51	UNSCHEDULED SYSTEM INSPECTION	4LVH	RX UNIT			1.00	08/16/2012	R/R LEFT CCTV RECIEVER		27	DEFECTIVE	RR	REMOVED AND REPLACED	R1
4333617	3340	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LVFE	CAMERA			1.00	08/15/2012	T/S FOUND DISCONNECTED CABLE				TS	TROUBLESHOOT	R1
	3768	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LVFE	CAMERA			1.00	08/15/2012	T/S FOUND DISCONNECTED CABLE				TS	TROUBLESHOOT	R1
4333944	3632	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	09/19/2012					IN	INSPECTED	R1
		D			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	09/19/2012					IN	INSPECTED	R1
4333945	3768	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	09/07/2012					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	09/07/2012					IN	INSPECTED	R1
4333947	3215	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	08/18/2012					IN	INSPECTED	R1
	3340	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	08/20/2012					IN	INSPECTED	R1
4334147	3444	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			1.00	08/15/2012	R/R LEFT RECIEVER		27	DEFECTIVE	RR	REMOVED AND REPLACED	R1
4334149	3444	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVG	TX UNIT			1.00	08/16/2012	R/R COAX WIRE FROM L/H	TRANSMITTER TO VDA	05	BROKEN	RR	REMOVED AND REPLACED	R1
4337906	1209	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			3.00	09/24/2012					IN	INSPECTED	R1
		E			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	09/24/2012					IN	INSPECTED	R1
4337910	4154	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	09/19/2012					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	09/19/2012					IN	INSPECTED	R1
4337914	4154	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	09/20/2012					IN	INSPECTED	R1
		D			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	09/20/2012					IN	INSPECTED	R1
4337917	3215	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	10/06/2012					IN	INSPECTED	R1
	3850	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	10/05/2012					IN	INSPECTED	R1
4337923	3661	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	09/22/2012					IN	INSPECTED	R1
	4147	A			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	09/20/2012					IN	INSPECTED	R1
4338541	3595	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	10/11/2012					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	10/11/2012					IN	INSPECTED	R1
4341332	3910	B			N10	T-2 PM 4,500 MILE PKG	2LVFF	WIRING/CONNECTIONS	'A' CAR		4.00	09/09/2012	NO MAGE DUE TO BROKEN COAXLE	CABLE R/R COAX CABLE T/S IS GOOD NOW.			RR	REMOVED AND REPLACED	R1
4341337	3401	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	09/11/2012					IN	INSPECTED	R1
4341345	3909	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	11/23/2012					IN	INSPECTED	R1
	4095	C			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			2.00	11/23/2012					IN	INSPECTED	R1
4345188	3215	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA	CCTV CAMERA (B-CAB)		4.75	10/21/2012	T/S CAMERA 4,		78	OUT OF SPECIFICATION	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA	CCTV CAMERA (B-CAB)		7.00	10/22/2012	T/S CAMERA 4,		78	OUT OF SPECIFICATION	TS	TROUBLESHOOT	R1
	3781	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA	CCTV CAMERA (B-CAB)		3.50	10/19/2012	T/S CAMERA 4, NOT WORKING-	FOUND CORROSSION ON PINS-NEEDSBE CLEANED AND TESTED	78	OUT OF SPECIFICATION	TS	TROUBLESHOOT	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
	3828	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (B-CAB)	6.75	10/23/2012	T/S CAMERA 4, CLEANED CONTACTS		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	3913	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (B-CAB)	3.00	10/19/2012	T/S CAMERA 4, PROBLEM TO BE @	205 BOX ON ROOF,NEEDS MORE T/S	78	OUT OF SPECIFICATION	TS	TROUBLESHOOT	R1
4345712	3850	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			1.50	09/04/2012	BLACK SCREEN/ R/R UNIT, WORKS				RR	REMOVED AND REPLACED	R1
4346472	3831	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.50	10/03/2012					IN	INSPECTED	R1
4346477	3768	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.10	09/11/2012					IN	INSPECTED	R1
	3828	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	09/12/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	09/12/2012					IN	INSPECTED	
4347913	2881	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	09/22/2012					IN	INSPECTED	R1
	3607	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			2.00	09/29/2012					IN	INSPECTED	R1
	3768	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	09/28/2012					IN	INSPECTED	R1
	3850	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	09/20/2012					IN	INSPECTED	R1
4350661	4154	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	10/17/2012					IN	INSPECTED	R1
4350672	3633	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	09/24/2012					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	09/24/2012					IN	INSPECTED	
4351322	1209	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT		'A' CAR	0.50	09/15/2012	T/S DARK MONITOR,USED CROSS	OVER CABLE TO TEST,MONITOR OK,NEEDS FURTHWR T/S.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4352206	3721	E			N10	T-2 PM 4,500 MILE PKG	2LVE	CAMERA			3.50	09/25/2012	ADJ B-RT CAMERA INTO FOCUS		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4354304	1209	D			S10	COMMUNICATION FAILURE	2LVFF	WIRING/CONNECTIONS			0.50	09/21/2012	FOUND SHORTED/BURNED CONNECTOR	FROM TRANSMITTER TO 8A78 CA1	84	SHORTED	CK	CHECKED	R1
		E			S10	COMMUNICATION FAILURE	2LVFF	WIRING/CONNECTIONS			0.50	09/21/2012	R/R CABLE CAMERA 1 TO CONTROL	BOX	84	SHORTED	RR	REMOVED AND REPLACED	
4354535	3789	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	10/24/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	10/24/2012					IN	INSPECTED	
4355276	3913	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT			0.25	09/24/2012	TESTED-NDF		86	SUSPECTED FAILURE	TT	TESTED	R1
4355360	3522	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	10/05/2012					IN	INSPECTED	R1
	3595	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	10/19/2012					IN	INSPECTED	R1
4355363	3750	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	09/30/2012					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	09/30/2012					IN	INSPECTED	
4355369	3449	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.25	10/31/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	10/31/2012					IN	INSPECTED	
4356008	3785	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	09/30/2012					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	09/30/2012					IN	INSPECTED	
4356546	3785	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.75	11/25/2012					IN	INSPECTED	R1
4356559	3801	B			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	11/07/2012					IN	INSPECTED	R1
		D			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	11/07/2012					IN	INSPECTED	
	3917	B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			6.00	11/11/2012					IN	INSPECTED	R1
4358661	3756	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.01	12/14/2012	WORKING NORMAL NOW		86	SUSPECTED FAILURE	IN	INSPECTED	R1
	3919	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.01	12/14/2012	WORKING NORMAL NOW		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4358835	4096	K			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			0.80	10/06/2012	TIGHTEND LOOSE MONITORS		57	LOOSE	TI	TIGHTENED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4362518	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	4LV	CCTV EQUIPMENT	.	.	0.75	10/02/2012	T/S CCTV BLUE SCREENS CCTV	SYSTEM WORKING AS INTENDED	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4362539	3790	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	1.00	10/02/2012	CHECKED MONITOR		69	NO DEFECT FOUND	CK	CHECKED	R1
4363237	3797	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	10/25/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	4.00	10/25/2012					IN	INSPECTED	
4363242	3419	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	10/10/2012					IN	INSPECTED	R1
	3789	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	10/09/2012					IN	INSPECTED	R1
4364402	1209	A			S08	CARBODY/CAR/CAB INTER FAILURE	2LV	CCTV EQUIPMENT	.	MASTER CONTROLLER ('A' CAR)	0.50	10/06/2012	CHECKED MDH,OPERATES PROPERLY		61	MALFUNCTION/REASON UNKNOWN	CK	CHECKED	R1
4364715	3669	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	11/14/2012					IN	INSPECTED	R1
	3700	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	11/14/2012					IN	INSPECTED	R1
	3801	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	11/14/2012					IN	INSPECTED	R1
4365397	3419	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	10/17/2012					IN	INSPECTED	R1
	3789	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	10/17/2012					IN	INSPECTED	R1
4366088	3094	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.	.	1.00	10/09/2012	CHECKED-NDF		86	SUSPECTED FAILURE	ND	NO DEFECT FOUND	R1
4366898	4095	O			N30	T-4 PM 9,000 MILE PKG	4LVFE	CAMERA, EXTERIOR	.	.	2.00	10/19/2012	ADJUSTED LEFT EXTERIOR CAMERA		27	DEFECTIVE	AJ	ADJUSTED	R1
4367986	3721	B			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	0.50	02/04/2013	CHECK CCTV CAMS & VIEWS WERE	FINE	86	SUSPECTED FAILURE	TT	TESTED	R1
4368060	3632	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	11/26/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	11/26/2012					IN	INSPECTED	
4368951	3632	J			N01	T-1 PM 9,000 MILE PKG	222460	WIRING/CONNECTIONS	.	.	4.00	10/23/2012	R/R CCTV MONITOR EXTENSION	CABLE	27	DEFECTIVE	RR	REMOVED AND REPLACED	R1
4369549	3632	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	11/13/2012					IN	INSPECTED	R1
		E			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	11/13/2012					IN	INSPECTED	
4371036	3398	A			A09	MISC - FABRICATION	2LV	CCTV EQUIPMENT	.	.	8.00	10/17/2012	T/S-REWIRE TEST BENCH		27	DEFECTIVE	RE	REPAIRED	R2
		B			A09	MISC - FABRICATION	2LV	CCTV EQUIPMENT	.	.	6.00	10/18/2012	REWIRE TEST BENCH		27	DEFECTIVE	RE	REPAIRED	
4371553	4096	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT	.	'A' CAR	0.80	10/20/2012	JUMPED CABLES MONITOR IS GOOD	SUSPECT-CONTROL BOX BUT NO PARTS IN STORES	27	DEFECTIVE	TS	TROUBLESHOOT	R1
4371629	3449	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	12/13/2012					IN	INSPECTED	R1
	4154	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	12/15/2012					IN	INSPECTED	R1
4371914	3850	J			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV	.	.	1.00	11/16/2012					IN	INSPECTED	R1
4373243	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT	.	.	0.50	10/23/2012	T/S BLUE SCREEN LEFT & RIGHT	FORWARD BACK,AUX'D BACK ON NO DEFECT	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4373333	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT	.	.	0.75	10/23/2012	T/S DARK LEFT HAND MONITOR ON	A-END FOUND PLUG FROM MONITOR DESTROYED	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S52	CCTV DATA PACK/EVENT RECORDER	2LVFF	WIRING/CONNECTIONS	.	.	2.00	10/23/2012	R/R JUMPER CABLE FROM CONTROL	BOX TO MONITOR	19	CRUSHED/DESTROYED	RR	REMOVED AND REPLACED	
4374074	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	222000	CCTV EQUIPMENT	.	.	10.00	10/08/2012	WORK ON AR RACK BUILD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	R1
		B			S52	CCTV DATA PACK/EVENT RECORDER	222000	CCTV EQUIPMENT	.	.	10.00	10/09/2012	WORK ON AR RACK BUILD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		C			S52	CCTV DATA PACK/EVENT RECORDER	222000	CCTV EQUIPMENT	.	.	10.00	10/10/2012	WORK ON AR RACK BUILD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		D			S52	CCTV DATA PACK/EVENT RECORDER	222000	CCTV EQUIPMENT	.	.	10.00	10/11/2012	WORK ON AR RACK BUILD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
		E			S52	CCTV DATA PACK/EVENT RECORDER	222000	CCTV EQUIPMENT			10.00	10/12/2012	WORK ON AR RACK BUILD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
		F			S52	CCTV DATA PACK/EVENT RECORDER	222000	CCTV EQUIPMENT			10.00	10/24/2012	WORK ON AR RACK BUILD		81	SCHEDULED CHANGE/INSTALLATION	MO	MODIFIED	
4375313	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVA1	CAMERA HOUSING		CCTV CAMERA (A-CAB)	0.75	10/28/2012	CLEAN CAMERA LENS ON LRV 402		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4375407	3828	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	10/30/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	10/31/2012					IN	INSPECTED	
4375587	3419	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	11/07/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	11/07/2012					IN	INSPECTED	
4376983	3750	J			N04	T-1 PM 40,500 MILE PKG	MIL312	TEST: CCTV			1.00	11/27/2012					IN	INSPECTED	R1
4379964	3398	A			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			3.00	11/14/2012	PROGRAM MONITORS		27	DEFECTIVE	PG	PROGRAMMED	R2
4379965	3398	A			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			1.00	11/01/2012	FORMAT DATA PACKS		27	DEFECTIVE	PG	PROGRAMMED	R2
		B			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			2.00	11/02/2012	FORMAT DATA PACKS		27	DEFECTIVE	PG	PROGRAMMED	
		C			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			2.00	11/08/2012	FORMAT DATA PACKS		27	DEFECTIVE	PG	PROGRAMMED	
		D			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			1.00	11/19/2012	FORMAT DATA PACKS		27	DEFECTIVE	PG	PROGRAMMED	
4381222	3394	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/18/2012					IN	INSPECTED	R1
4381223	3790	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	11/08/2012					IN	INSPECTED	R1
4381230	1209	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	12/09/2012					IN	INSPECTED	R1
	4120	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.20	12/10/2012					IN	INSPECTED	R1
4381476	3828	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	11/23/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	11/23/2012					IN	INSPECTED	
	3919	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	11/24/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	11/24/2012					IN	INSPECTED	
4381477	3917	C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/05/2012					IN	INSPECTED	R1
	4147	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/05/2012					IN	INSPECTED	R1
4382164	3631	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	11/11/2012					IN	INSPECTED	R1
	3632	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	11/12/2012					IN	INSPECTED	R1
4382171	3419	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	12/06/2012					IN	INSPECTED	R1
	3828	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/06/2012					IN	INSPECTED	R1
4382947	3785	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/07/2012					IN	INSPECTED	R1
	3909	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	12/10/2012					IN	INSPECTED	R1
4382952	4147	G			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			2.00	11/13/2012	FABRICATE 12 FOOT CCTV CAMERA	HOUSING CLEANING DEVICES			FB	FABRICATED	R1
4383284	3632	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	0.50	12/05/2012	CHECK VIDEO DATA & ALL 4	CAMERAS SEEM TO BE OK	86	SUSPECTED FAILURE	IN	INSPECTED	R1
4384513	3583	A			S10	COMMUNICATION FAILURE	4LVH	RX UNIT		'A' CAR	0.75	11/10/2012	ADJ. SCREW, GOT VIEW		61	MALFUNCTION/REASON UNKNOWN	AJ	ADJUSTED	R1
4384540	4147	B			N04	T-1 PM 40,500 MILE PKG	MIL312	TEST: CCTV			0.75	12/06/2012					IN	INSPECTED	R1
4385312	3909	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE1	MOUNT/HOUSING/MIRROR			0.50	11/12/2012	CLEARED CONDENSATION FROM	CAMERA HOUSING	93	WATER DAMAGE/INFILTRATION	CE	CLEARED	R1
4385359	3789	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	11/27/2012					IN	INSPECTED	R1
	3850	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	11/26/2012					IN	INSPECTED	R1
4385948	3394	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	12/07/2012					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4385950	3789	D			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/07/2012					IN	INSPECTED	
		F			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/18/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/18/2012					IN	INSPECTED	
4385954	3850	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	01/04/2013					IN	INSPECTED	R1
	6501	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			4.00	01/04/2013					IN	INSPECTED	R1
4388256	3917	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	12/23/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	12/23/2012					IN	INSPECTED	
4389704	1209	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/30/2012					IN	INSPECTED	R1
		D			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/30/2012					IN	INSPECTED	
4390282	1209	J			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV			1.00	01/14/2013					IN	INSPECTED	R1
4390696	2701	B			S23	CCTV/APC/EVENT RECORDER FAILS	4LVA1	CAMERA HOUSING		CCTV CAMERA (A-CAB)	2.00	11/24/2012	SEALED CAMERA HOUSING		93	WATER DAMAGE/INFILTRATION	SL	SEALED	R1
4390998	3917	C			N30	T-4 PM 9,000 MILE PKG	4LVFF	WIRING/CONNECTIONS			0.25	12/02/2012	LOOSE CONNECTION ON CAM #3		57	LOOSE	TI	TIGHTENED	R1
4391852	3398	A			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			2.00	11/26/2012	PROGRAMS DVR'S,		27	DEFECTIVE	PG	PROGRAMMED	R2
4393017	3790	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB)	1.00	11/28/2012	INSP. NDF		69	NO DEFECT FOUND	IN	INSPECTED	R1
4393020	3790	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT			1.00	11/28/2012	NDF		69	NO DEFECT FOUND	ND	NO DEFECT FOUND	R1
4393142	3394	J			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV			1.00	01/01/2013					IN	INSPECTED	R1
4394021	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			1.50	11/29/2012	T/S DARK MONITOR RIGHT,DEAD	MONITOR LEFT FOUND RIGHT MONI-TOR WORKS PROPERLY WHEN CARD BOARD REMOVED FROM FRONT BACK SWITCH PUT CARDBOARD BACK IN WORKING PROPERLY,LEFT MONITOR TRIED SWAPPING MONITOR-NO HELP/CHECK ALL ASSOCIATED WIRING, COAX,ETC OK TRIED ANOTHER CONTROL BOX-WORKED PROPERLY	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4394158	3395	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/05/2012					IN	INSPECTED	R1
	3419	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/05/2012					IN	INSPECTED	R1
4397656	3522	A			S10	COMMUNICATION FAILURE	222100	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	0.50	12/04/2012	CAMERA WORKING FINE		61	MALFUNCTION/REASON UNKNOWN	IN	INSPECTED	R1
4397729	3632	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/27/2012					IN	INSPECTED	R1
	3721	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/23/2012					IN	INSPECTED	R1
4398473	4147	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	12/07/2012					IN	INSPECTED	R1
	4154	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	12/06/2012					IN	INSPECTED	R1
4399022	3909	C			N00	T-1 PM 4,500 MILE PKG	222455	MOUNT/HOUSING/MIRROR			0.50	12/23/2012	CLND & RESEALED SIDE VIEW CAN	HOUSING	93	WATER DAMAGE/INFILTRATION	SL	SEALED	R1
4399023	3789	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/10/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/10/2012					IN	INSPECTED	
4399769	3449	C			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/27/2012					IN	INSPECTED	R1
		E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	12/27/2012					IN	INSPECTED	

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4400381	3924	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	2.00	12/08/2012	T/S A-MONITOR DARK CHECK CON-	NECTIONS AND WIRING FOUND VIDEO WIRES TO RX'S ON A-END HAD WIRES STUCK OUT PAST TERM-INALS & WERE FALIREED & TOUCH-ING BETWEEN + - CUT OFF AND A LOT OF THE INTERFERENCE WENT AWAY FOUND RX'S WERE MISADJUSTADJUSTED & ALL MONITOR PICTUREARE NOW WORKING AS THEY SHOULDBE.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	4120	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	1.20	12/07/2012	R/R ROCKER SWITCH,NO CHANGE	MONITOR STILL HS OMAGE ONCE ROCKER SWITCH IS DEPRESSED	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4400426	3522	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	12/13/2012					IN	INSPECTED	R1
	3850	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	12/12/2012					IN	INSPECTED	R1
4400853	3394	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	12/19/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	12/19/2012					IN	INSPECTED	R1
	4921	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	12/19/2012					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	12/19/2012					IN	INSPECTED	R1
4401236	3522	A			S10	COMMUNICATION FAILURE	2LVFE	CAMERA	.	.	0.70	12/11/2012	ADJ. CAMERA		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4401342	3395	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	12/28/2012					IN	INSPECTED	R1
	6501	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	12/30/2012					IN	INSPECTED	R1
4401350	3340	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	01/02/2013					IN	INSPECTED	R1
4401884	3522	G			N10	T-2 PM 4,500 MILE PKG	2LVFE	CAMERA	.	.	1.00	12/26/2012	R/R B LEFT SIDE VIEW CAMERA		53	LEAKING/CONDENSATION	SL	SEALED	R1
4401885	3790	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.50	12/18/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	2.00	12/18/2012					IN	INSPECTED	R1
4403179	3917	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	01/15/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	01/15/2013					IN	INSPECTED	R1
4403182	3419	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	01/08/2013					IN	INSPECTED	R1
	3828	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	01/08/2013					IN	INSPECTED	R1
4403268	3735	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LV	CCTV EQUIPMENT	.	.	3.00	12/21/2012	TS CAM 3 NOT 2 LOOKING @ DATA	PACK ON OFFICE COMPUTER ON DEC15TH CAM PICTURE COMPLETELY SCRAMBLED THEN LOOKING @ DEC20HAD A PICTURE BUT PIXELATED LIKE INTERFERENCE. CHCKD CAM W/ PORTABLE UNIT-CLR PICTURE CHCKD AT RECORDER & IT SHOWED THE INTERFERENCE & USING THE LAPTOP WAS WORTHLESS			TS	TROUBLESHOOT	R1
	3785	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LV	CCTV EQUIPMENT	.	.	6.00	12/22/2012	T/S BAD IMAGE ON CAM3. LCD-	MONITOR NOT WORKING. COBBLED ONE TOGETHER WITH PARTS, FND CORROSION @ X205J12-27 PLUG, CLND UP & RETESTED GOOD. FORSOME REASON LOST IMAGE @ CAM #4 NEEDS T/S	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
		B			S51	UNSCHEDULED SYSTEM INSPECTION	2LVFF	WIRING/CONNECTIONS	.	.	1.00	12/22/2012	CLND CORRODED PLUG		16	CORRODED	CL	CLEANED/WASHED/FUMIGATED	
		C			S51	UNSCHEDULED SYSTEM INSPECTION	2LVA	CAMERA	.	CCTV CAMERA (A-CAB ARTIC AREA)	0.50	01/13/2013	TESTED OK-NDF		86	SUSPECTED FAILURE	TT	TESTED	
	3917	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LVA	CAMERA	.	CCTV CAMERA (FORWARD FACING)	2.00	12/22/2012	T/S NO CAMERA #4		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4403710	2636	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	01/28/2013					IN	INSPECTED	R1
4403946	4147	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.75	01/23/2013					IN	INSPECTED	R1
4403947	3630	E			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	01/27/2013					IN	INSPECTED	R1
4403949	331	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	01/07/2013					IN	INSPECTED	R1
	3340	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	01/05/2013					IN	INSPECTED	R1
	3828	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	01/05/2013					IN	INSPECTED	R1
4403950	3741	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	01/16/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	01/16/2013					IN	INSPECTED	R1
4404210	3340	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	12/20/2012					IN	INSPECTED	R1
	3607	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	12/21/2012					IN	INSPECTED	R1
4404872	3726	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	01/19/2013					IN	INSPECTED	R1
	3909	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	01/20/2013					IN	INSPECTED	R1
4405306	3631	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	12/24/2012					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	12/24/2012					IN	INSPECTED	R1
4405918	3756	B			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT	.	.	6.50	12/22/2012	BUILD PORTABLE MONITOR AND	CONNECT TO EACH COAX AT THE RECORDER CAM 1,2,3&4 ARE ALL FOCUSED & SENDING CLEAR SIGNAL/PULL DATA PACK & CHCK IMAGES. NO DEFECT NOTED	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	4120	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT	.	.	1.50	12/20/2012	T/S ROAD RECORDER 6000 PRO.	OBSERVED UNIT CYCLING ON&OFF REPEATEDLY INVESTIGATED DIFFERENT SCENARIOS W/ P.T.U, IT WOULD APPEAR THAT UNIT REQUIRES RR	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4405966	3850	A			S10	COMMUNICATION FAILURE	2LV	CCTV EQUIPMENT	.	CCTV CAMERA (B-CAB ARTIC AREA)	1.75	12/19/2012	BAD IMAGE, TESTD @ CAMERA-OK	SWAP CHANNEL 3 TO CHANNEL 4. PROBLEM MOVED TO CHANNEL 4. CONNECTED LCD TEST SCREEN TO DVR END-CAM 3 BAD IMAGE IT CAN BE VIEWABLE AT TIMES BUT I DID SEE IT GO ALMOST COMPLETELY BLACK/PURPLISH NEEDS TO COME IN SHOP FOR FURTHER COAX INSPECTION. REPEATER SEE HISTORY			TT	TESTED	R1
4406631	3924	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	01/14/2013					IN	INSPECTED	R1
	4147	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	01/11/2013					IN	INSPECTED	R1
4406637	3395	M			N30	T-4 PM 9,000 MILE PKG	4LVFG	MOUNTS/HARDWARE	.	.	0.50	01/04/2013	R/R MONITOR BRACKET		05	BROKEN	RR	REMOVED AND REPLACED	R1
4407208	2636	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	01/10/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	01/10/2013					IN	INSPECTED	R1
4408047	3828	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	01/14/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	01/14/2013					IN	INSPECTED	R1
4408665	3721	H			N10	T-2 PM 4,500 MILE PKG	2LVFG	MOUNTS/HARDWARE	.	.	0.50	01/04/2013	REPLACED MISSING VISORS		66	MISSING	IO	INSTALLED ONLY	R1
4408670	3633	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	01/23/2013					IN	INSPECTED	R1
	3850	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	01/20/2013					IN	INSPECTED	R1
4409456	3721	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	01/04/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	01/04/2013					IN	INSPECTED	R1
4409457	4154	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	01/19/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	01/19/2013					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4409460	3633	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.		1.00	12/30/2012					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.		1.00	12/30/2012					IN	INSPECTED	
4409875	3661	B			N04	T-1 PM 40,500 MILE PKG	MB312	TEST: CCTV	.		1.00	01/26/2013					IN	INSPECTED	R1
4410222	4120	A			S10	COMMUNICATION FAILURE	4LVFE1	MOUNT/HOUSING/MIRROR	.		1.40	12/30/2012	REMOVED CAMERA COVERS, WIPED	INTERIOR, KEYED UP, COMPARED TO 418'S MONITORS, NEARLY IDENTICAL IMAGES	15	CONTAMINATED	CL	CLEANED/WASHED/FUMIGATED	R1
4410613	3633	C			S11	DOOR FAILURE	2LV	CCTV EQUIPMENT	.		1.50	01/05/2013	T/S NO IMAGE ON RIGHT MONITOR	B CAB	65	MISADJUSTED/MISALIGNED	TS	TROUBLESHOOT	R1
4412551	3917	G			N20	T-3 PM 4,500 MILE PKG	2LVA	CAMERA	.	CCTV CAMERA (B-CAB ARTIC AREA)	0.50	01/16/2013	ADJUSTED CAMERA #3		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
		H			N20	T-3 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT	.		1.50	01/16/2013	T/S CAMERA #2 FOUND LOOSE COAX		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	
4413049	3631	A			N99	DEFERRED PM ITEMS 9/2001	2LV	CCTV EQUIPMENT	.		0.50	01/23/2013	PERFORMED PM ITEM 211		81	SCHEDULED CHANGE/INSTALLATION	IN	INSPECTED	R1
4413923	4154	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.		1.00	01/25/2013					IN	INSPECTED	R1
		D			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.		1.00	01/25/2013					IN	INSPECTED	
4413925	3828	B			N20	T-3 PM 4,500 MILE PKG	2LVA	CAMERA	.	CCTV CAMERA (A-CAB ARTIC AREA)	0.50	01/14/2013	FOCUSED CAMERA 2 IMAGE		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4414127	3398	A			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		1.00	01/03/2013	TEST CONTROL BOXES		27	DEFECTIVE	PG	PROGRAMMED	R2
		B			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		5.00	01/04/2013	TEST MONITORS		27	DEFECTIVE	PG	PROGRAMMED	
		C			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		2.00	01/21/2013	TEST		27	DEFECTIVE	PG	PROGRAMMED	
		D			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		1.00	01/22/2013	TEST		27	DEFECTIVE	PG	PROGRAMMED	
		E			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		1.00	01/28/2013	FORMAT DATA PACKS		27	DEFECTIVE	PG	PROGRAMMED	
		F			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		2.00	01/30/2013	TEST		27	DEFECTIVE	PG	PROGRAMMED	
		G			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		1.00	02/01/2013	FORMAT DATA PACKS		27	DEFECTIVE	PG	PROGRAMMED	
		H			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		1.00	02/04/2013	ATTEMPT TO FORMAT DATA PACKS		27	DEFECTIVE	PG	PROGRAMMED	
		I			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT	.		3.00	02/05/2013	PROGRAM MONITORS, TEST		27	DEFECTIVE	PG	PROGRAMMED	
4414538	3419	A			N04	T-1 PM 40,500 MILE PKG	MB312	TEST: CCTV	.		0.50	01/15/2013					IN	INSPECTED	R1
4414568	3215	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.		0.75	01/14/2013					IN	INSPECTED	R1
	3340	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.		1.00	01/14/2013					IN	INSPECTED	R1
4414571	4147	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.		0.50	01/09/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.		0.75	01/09/2013					IN	INSPECTED	
4414773	3340	I			N10	T-2 PM 4,500 MILE PKG	2LVFE	CAMERA	.		0.50	01/11/2013	ADJ. B RT SIDE CAMERA				AJ	ADJUSTED	R1
4414975	3921	J			N10	T-2 PM 4,500 MILE PKG	2LVFF	WIRING/CONNECTIONS	.	'A' CAR	0.50	01/13/2013	NDF		57	LOOSE	RX	REMOVED/REPAIRED/REINSTALLED	R1
4415569	3750	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.		0.50	01/12/2013					IN	INSPECTED	R1
	3785	A			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.		1.00	01/13/2013					IN	INSPECTED	R1
4416440	3693	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.		1.25	01/09/2013	CLEANED COVER LENS INSIDE/OUT	STILL DIM HOWEVER WITH COVER REMOVED THE MONITOR IS AT NORMAL BRIGHTNESS LOOKED FOR NEW HOUSING HEATER FOUND NONE WAS RAINING TO HARD TO REPLACE THE CAMERA IN THE YARD, NEEDED CAR FOR PULL OUT, REPLACE COVER WITH DRY ONE FROM STORES, THIS SHOULD DO UNTIL TO NIGHT	93	WATER DAMAGE/INFILTRATION	TS	TROUBLESHOOT	R1
	3850	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.		0.50	01/09/2013	IMAGE WAAS FINE AT NIGHT, HARD	'TO TELL WHEN IN BLACK & WHITE NO CONDENSATION FOUND SO MAYBE NEW HOUSING DID THE TRICK			IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4416712	3721	H			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR			1.00	01/15/2013	FIXED IMPROPERLY INSTALLED	MONITOR HARDWARE	63	MECHANICAL FAILURE	RE	REPAIRED	R1
4416715	2636	O			N30	T-4 PM 9,000 MILE PKG	2LVFE	CAMERA			0.75	01/23/2013	ADJ. LH CCTV CAMERA		78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1
4417541	3631	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	01/13/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/13/2013					IN	INSPECTED	
4417547	3661	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	01/19/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	01/19/2013					IN	INSPECTED	
4418749	3909	G			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			2.00	01/17/2013	T/S B-LEFT MONITOR,FLICKER	MOVED CABLES PROBLEM DISAPPEAR	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4418935	2701	A			S10	COMMUNICATION FAILURE	4LVG	TX UNIT			0.75	01/12/2013	ADJ. RX- WORKING GOOD		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4420583	3921	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.75	02/04/2013					IN	INSPECTED	R1
4421782	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.75	01/17/2013	SOMETIMES WHEN YOU COUPLE TO	A CAR WITH NO CAMERA WILL NOTGET A GOOD PICTURE VIEW	86	SUSPECTED FAILURE	CK	CHECKED	R1
4421783	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.75	01/18/2013	CHECKED SWITCH TO REAR AND	BACK TO FRONT AND IT STARTED WORKING BETTER THAN THE LEFT.	86	SUSPECTED FAILURE	CK	CHECKED	R1
4421866	3631	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	01/29/2013					IN	INSPECTED	R1
		D			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/29/2013					IN	INSPECTED	
4421867	3924	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	01/29/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	01/29/2013					IN	INSPECTED	
4422252	3340	B			S02	CONVERTER FAILURE	222000	CCTV EQUIPMENT		'A' CAR	2.00	01/21/2013	T/S A CAB, LT MONITOR BAD,	REPROGRAMMED-OK			TS	TROUBLESHOOT	R1
4423771	3909	A			S10	COMMUNICATION FAILURE	4LVFE1	MOUNT/HOUSING/MIRROR			1.00	01/22/2013	CLEANED OUT MOISTURE FROM	CAMERA HOUSING	53	LEAKING/CONDENSATION	CL	CLEANED/WASHED/FUMIGATED	R1
4425379	3094	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		'A' CAR	0.25	01/25/2013	303 DOES NOT HAVE SIDE VIEW	CAMERA INSTALLED-	86	SUSPECTED FAILURE	ND	NO DEFECT FOUND	R1
4426385	3094	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT			4.00	01/29/2013	T/S CCTV SYSTEM, 2 BAD CONTROL	BOXES, 1 BAD MONITOR	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4426487	3721	G			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			1.00	02/04/2013	T/S RT MONITOR SHOWING WRONG	PICTURE	81	SCHEDULED CHANGE/INSTALLATION	TS	TROUBLESHOOT	R1
4428612	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.50	01/31/2013	T/S RIGHT MONITOR B-END DARK	AUXED OFF AND BACK ON OK NOW	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4430533	4147	D			N11	T-2 PM 9,000 MILE PKG	2LV	CCTV EQUIPMENT			4.00	02/08/2013	T/S B-CCTV BREAKER NOT ABLE TO	RESET ALREADY REPAIRED BY SWING SHIFT,PUT CABS BACK TOGETHER	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4432730	3781	A			S10	COMMUNICATION FAILURE	4LVH	RX UNIT			0.75	02/05/2013	ADJ. RECEIVER UNIT FOR RIGHT	MONITOR WAS TO BRIGHT	65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4437085	3789	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT			0.50	02/12/2013	CHECKED RECORDER AND GREEN	LIGHT WAS WORKING-NDF	86	SUSPECTED FAILURE	ND	NO DEFECT FOUND	R1
4437160	3340	F			N20	T-3 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			2.00	02/27/2013	R/R DIODE				RR	REMOVED AND REPLACED	R1
	3850	F			N20	T-3 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			2.00	02/26/2013	R/R DIODE AND TEST				RR	REMOVED AND REPLACED	R1
4437611	3781	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			0.75	02/13/2013	T/S RIGHT SIDE REARVIEW	MONITOR,	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			0.75	02/13/2013	R/R RECEIVER		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	
4438222	3449	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.50	02/13/2013	REAR VIEW WAS BLUE SEPERATED	AND COUPLED 240->230A THEN 240=BLUE 249A RT GREY 322A->230A BRT BAD ON BOTH OF OF THEM RECOUPLED 322B->240B 322 OK 240B BLUE 249 & 230 HAVE NO RRAR VIEW.			TT	TESTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
	3911	B			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.50	02/14/2013	REMOVE UNCOUPLED TRIGGER-TEST	REAR VIEW-OK			TT	TESTED	R1
	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			2.50	02/13/2013	T/S 240B LEFT MONITOR BLUE IN	REAR VIEW AS A SINGLE EVERY-THING WORKS AS INTENDED ON BOTH CARS, COUPLED 240B LEFT MONITOR BLUE IN SPLIT AND REARVIEW, CHECK ASSOCIATED WIRING. OK TRIED A DIFFERENT COAX CON-NECTOR FROM CONTROL BOX TO RX NO CHANGED SWAPPED RECEIVERS LEFT & RIGHT AT COAXS, LEFT REAR IMGAGE SHOWED ON RIGHT REAR MONITOR, RIGHT REAR IMAGE BLUE RX 8N2 IS BAD	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4438490	3632	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			3.00	02/15/2013	T/S CODE 7069, FOUND RELAY	47-K01 NOT ENERGIZED	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			1.00	02/15/2013	R/R FAULTY 47-K01 RELAY BOARD		35	ELECTRICAL FAILURE	RR	REMOVED AND REPLACED	
	3669	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			1.00	02/15/2013	T/S CODE 7069 TRIED TO RESET	WITH BREAKER AND A NEW PACK- THEN CHECKED HISTORY ON IT. THIS IS A REPEATER, FURTHER T/SNEEDED.	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4439344	3693	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS			1.75	02/18/2013	T/S BLUE SCREEN ON CCTV-	RE INSTALLED VIDEO CABLE ON 238 AND SEE RO#4439343 FOR REPAIRS ON 245	10	CCU/TRANSMIT/RECEPTION FAILURE	TS	TROUBLESHOOT	R1
4439572	3801	B			N20	T-3 PM 4,500 MILE PKG	2LVFF	WIRING/CONNECTIONS			2.00	02/26/2013	REPAIR COAX WIRES FOR CAMERA	3/4 @ BTCC ROOF TOP/@ RECORDER UNIT	35	ELECTRICAL FAILURE	RE	REPAIRED	R1
4440037	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			1.00	02/19/2013	FOUND TO BE BAD CONNECTION	BETWEEN AND MONITOR, CLEANED PINS, RECONNECTED OK REARVIEW DOESN'T WORK BECAUSE 303 DOESN'T HAVE CCTV (IT'S A COUPLED CAB)	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4440047	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	4LV	CCTV EQUIPMENT			1.00	02/19/2013	T/S LEFT MONITOR DARK/FUZZY IN	SPLIT ALSO SAME IN REAR, FOUND RX NEEDING ADJUST	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4440195	3632	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	03/05/2013					IN	INSPECTED	R1
4440600	3911	A			S08	CARBODY/CAR/CAB INTER FAILURE	222450	CAMERA			2.00	02/20/2013	ADJ FOCUS ON B-LEFT CAMERA	LENS FOR CLEAR IMAGE, ADJ CAMERA TO PROPER POSITION	65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4440780	3721	G			N10	T-2 PM 4,500 MILE PKG	2LVFE	CAMERA			1.00	02/27/2013	ADJ LEFT B-EXT SIDEVIEW CAMERA		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4440784	3785	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/23/2013					IN	INSPECTED	R1
	4154	C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/21/2013					IN	INSPECTED	R1
4441220	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.75	02/22/2013	CHECKED- WORKING		86	SUSPECTED FAILURE	CK	CHECKED	R1
4441280	1209	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/10/2013					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/10/2013					IN	INSPECTED	
4442791	908	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/07/2013					IN	INSPECTED	R1
	3726	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	03/07/2013					IN	INSPECTED	R1
4442795	3631	A			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	03/06/2013					IN	INSPECTED	R1
	3721	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/05/2013					IN	INSPECTED	R1
4443299	3860	I			N00	T-1 PM 4,500 MILE PKG	222100	CAMERA	CCTV CAMERA (A-CAB ARTIC AREA)		0.50	03/06/2013	CLEANED RE SEAL		93	WATER DAMAGE/INFILTRATION	CL	CLEANED/WASHED/FUMIGATED	R1
4443452	5093	B			S51	UNSCHEДУLED SYSTEM INSPECTION	2LVA1	CAMERA HOUSING	CCTV CAMERA (A-CAB)		1.00	02/26/2013	LEFT EXTERIOR CAMERA HOUSING	FOGGY INSIDE. DRIED & REPAIRED LEAKY SEAL	53	LEAKING/CONDENSATION	RE	REPAIRED	R1
4443710	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.50	02/26/2013	T/S DVR PROBLEM-FOUND DRIVE	MOUNT FAIL ON LCD SCREEN. REBOOTED BY WAY OF BREAKER. SAME.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4443824	3449	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/11/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/11/2013					IN	INSPECTED	
4443825	6501	N			N30	T-4 PM 9,000 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB)	3.50	03/06/2013	ADJ. EXT. LT SIDE CAMERA		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4447644	3632	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	03/11/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/11/2013					IN	INSPECTED	
4448096	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			1.75	03/03/2013	T/S -		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		C			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFG	MOUNTS/HARDWARE			0.50	03/03/2013	R/R MONITOR SWIVEL BRACKET		05	BROKEN	RR	REMOVED AND REPLACED	
4448316	3828	A			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			2.00	03/15/2013	T/S SIDE CCTV, R/R 8N1		61	MALFUNCTION/REASON UNKNOWN	IN	INSPECTED	R1
4448325	4147	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	03/10/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	03/10/2013					IN	INSPECTED	
4448347	5092	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.50	06/05/2013	FRONT CAMERA OPERATES WELL		69	NO DEFECT FOUND	ND	NO DEFECT FOUND	R1
4448426	4147	B			S23	CCTV/APC/EVENT RECORDER FAILS	4LVA	CAMERA, INTERIOR		CCTV RECORDING UNIT	0.75	03/10/2013	T/S CAMERA		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4448533	3449	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/14/2013					IN	INSPECTED	R1
	3632	C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/14/2013					IN	INSPECTED	R1
4449432	4147	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	03/18/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/18/2013					IN	INSPECTED	
4451347	5905	A			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			1.50	03/14/2013	T/S		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4451356	4120	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	03/19/2013					IN	INSPECTED	R1
	5091	B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	03/19/2013					IN	INSPECTED	R1
4452305	3449	O			N14	T-2 PM 40,500 MILE PKG	2LVFE	CAMERA		'B' CAR	1.00	03/27/2013	CLEANED CAMERA LENS		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
	3726	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	03/27/2013					IN	INSPECTED	R1
	5092	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/26/2013					IN	INSPECTED	R1
4452313	3631	B			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/19/2013					IN	INSPECTED	R1
		F			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	03/19/2013					IN	INSPECTED	
4452314	4924	A			N30	T-4 PM 9,000 MILE PKG	4LVFE	CAMERA, EXTERIOR		'A' TRUCK, LEFT SIDE	0.75	03/14/2013	ADJ. LT EXT. SIDE VIEW CCTV		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4453541	331	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/03/2013					IN	INSPECTED	R1
	3340	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	04/04/2013					IN	INSPECTED	R1
4453670	2701	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		CCTV CAMERA (B-CAB)	1.00	03/10/2013	T/S MONITORS-WORKING FINE		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4457539	3631	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	03/27/2013					IN	INSPECTED	R1
4457548	4924	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	03/26/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/26/2013					IN	INSPECTED	
4458125	5091	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	03/31/2013					IN	INSPECTED	R1
4459394	4095	C			N00	T-1 PM 4,500 MILE PKG	222455	MOUNT/HOUSING/MIRROR			0.50	03/29/2013	R/R RT SIDE CAMERA HOUSING	A-END	27	DEFECTIVE	RR	REMOVED AND REPLACED	R1
4459398	3595	F			N10	T-2 PM 4,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (A-CAB)	0.50	04/08/2013	ADJ. CAMERA #1		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4459768	4154	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.50	03/22/2013	CHECKED- NDF		86	SUSPECTED FAILURE	CK	CHECKED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4459770	4154	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			1.00	03/22/2013	WORKING-ADJ.		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4459831	5093	I			N00	T-1 PM 4,500 MILE PKG	222150	CAMERA HOUSING		CCTV CAMERA (B-CAB ARTIC AREA)	1.00	04/01/2013	REMOVE & DRY B-END CAMERA	HOUSING RIGHT SIDE	53	LEAKING/CONDENSATION	RE	REPAIRED	R1
4460047	3632	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/05/2013					IN	INSPECTED	R1
	5906	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/07/2013					IN	INSPECTED	R1
4460787	5091	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFE	CAMERA			0.50	04/18/2013	THIS CAR IS EQUIPPED WITH A	PANTOGRAPH CAMERA,IT IS NOT A FORWARD FACNG CAB CAM,THERE ISNO DEFECT.	69	NO DEFECT FOUND	ND	NO DEFECT FOUND	R1
4460795	3801	A			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			3.00	03/26/2013	REPAIR MONITORS		27	DEFECTIVE	RE	REPAIRED	R2
		B			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			2.00	03/27/2013	REPAIR MONITORS		27	DEFECTIVE	RE	REPAIRED	
		C			R01	BENCH REPAIR	2LV	CCTV EQUIPMENT			1.00	04/12/2013	REPAIR MONITORS		27	DEFECTIVE	RE	REPAIRED	
4461461	3419	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/17/2013					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/17/2013					IN	INSPECTED	
4463804	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT		'A' CAR	1.00	03/30/2013	FOUND LRV 408-SETTINGS & ADJUS	TMENT WERE OFF SET-SETTING & ADJUSTED,CAN NOW SEE REAR VIEW	65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4464044	4096	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT		'A' CAR	0.50	03/31/2013	CHECK CCTV GREEN N RED FLASHIN	WORKING AT THIS TIME	86	SUSPECTED FAILURE	IN	INSPECTED	R1
4467335	331	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/19/2013					IN	INSPECTED	R1
		C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/22/2013					IN	INSPECTED	
	5895	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/22/2013					IN	INSPECTED	R1
4468480	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		'B' CAR	1.00	04/04/2013	T/S MONITOR,		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	5905	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.50	04/05/2013	TESTED POWER SUPPLY AND SWITCH	ALL WORKING FINE	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.50	04/05/2013	R/R RIGHT MONITOR SCREEN		27	DEFECTIVE	RR	REMOVED AND REPLACED	
4468600	3632	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/01/2013					IN	INSPECTED	R1
	3917	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/01/2013					IN	INSPECTED	R1
	5899	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/01/2013					IN	INSPECTED	R1
4468993	4120	F			N10	T-2 PM 4,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	0.50	04/12/2013	RE-ADJUSTED A/CAB RIGHT CCTV		78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1
4469228	3721	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/17/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	04/17/2013					IN	INSPECTED	
4469440	3806	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/21/2013					IN	INSPECTED	R1
		B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/21/2013					IN	INSPECTED	
4469442	3449	G			N20	T-3 PM 4,500 MILE PKG	2LVFF	WIRING/CONNECTIONS			3.50	04/14/2013	T/S SIDE VIEW NO SPLIT SCREEN		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	4923	B			N20	T-3 PM 4,500 MILE PKG	2LVFF	WIRING/CONNECTIONS		'A' CAR	2.50	04/14/2013	T/S SV SPLIT SCREEN WILL GET	S/S WHEN KEYED DOWN, WAS GOING TO ORL THEN COUPLE B-END TO SEE IF IT WILL.	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	5096	B			N20	T-3 PM 4,500 MILE PKG	2LVFF	WIRING/CONNECTIONS		'A' CAR	1.00	04/14/2013	TESTED SIDE VIEW FOUND TO WORK	NORMAL THEN COUPLED FOR FURTHER TESTING,WORKED NORMAL	86	SUSPECTED FAILURE	TT	TESTED	R1
	5902	J			N20	T-3 PM 4,500 MILE PKG	2LVFF	WIRING/CONNECTIONS			0.75	04/13/2013	T/S SIDE VIEW NO SPLIT		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4471864	4154	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT			0.50	04/11/2013	REMOVE CARDBOARD JAMMED INTO	CONSOLE SWITCH AND MONITOR	98	BIO-HAZARD	RO	REMOVED ONLY	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4471965	1209	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	04/14/2013					IN	INSPECTED	R1
4472391	4154	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.75	04/29/2013					IN	INSPECTED	R1
4472642	3785	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/30/2013					IN	INSPECTED	R1
	4147	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/30/2013					IN	INSPECTED	R1
4472643	5091	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/26/2013					IN	INSPECTED	R1
	5899	E			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/24/2013					IN	INSPECTED	R1
4472847	3449	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/02/2013					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/02/2013					IN	INSPECTED	
4473321	3340	F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/27/2013					IN	INSPECTED	R1
	6501	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/26/2013					IN	INSPECTED	R1
4473861	5093	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/26/2013					IN	INSPECTED	R1
		B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/26/2013					IN	INSPECTED	
4475392	3750	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/06/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/06/2013					IN	INSPECTED	
4475900	3631	B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/28/2013					IN	INSPECTED	R1
	5093	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/27/2013					IN	INSPECTED	R1
4476049	4154	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.50	04/20/2013	CARDBOARD WAS JAMMED INTO	CONSOLE. REMOVED, WORKS	96	VANDALISM	RO	REMOVED ONLY	R1
4476688	4147	C			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			0.25	04/22/2013	AUX OFF/ON CAME BACK,BLURRY		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		D			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			0.25	04/22/2013	ADJ. RECEIVER-OK		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	
4476693	5902	A			V18	CARBODY OVERHAUL	2LVA	CAMERA		CCTV CAMERA (B-CAB)	4.50	09/09/2013	R/R CCTV CAMERA #4 REMOVE	AND CLEAN HOUSING REINSTALL AND ADJUST	16	CORRODED	RR	REMOVED AND REPLACED	R1
4476944	908	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/24/2013					IN	INSPECTED	R1
		C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/24/2013					IN	INSPECTED	
4477507	4921	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.75	05/02/2013					IN	INSPECTED	R1
4478212	3741	B			S51	UNSCHEDULED SYSTEM INSPECTION	2LVA	CAMERA		CCTV CAMERA (B-CAB)	2.00	04/28/2013	T/S CAMERA 4, NDF		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	3860	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LV	CCTV EQUIPMENT			1.00	05/06/2013	T/S #4 CAMERA, HAD A BAD PIN		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S51	UNSCHEDULED SYSTEM INSPECTION	2LVFF	WIRING/CONNECTIONS			1.00	05/06/2013	R/R REMALE CONNECTOR,TEST GOOD		27	DEFECTIVE	RR	REMOVED AND REPLACED	
	4147	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LV	CCTV EQUIPMENT			2.00	04/28/2013	T/S #4 CAMERA, BEING HELD FOR	MOD.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	4924	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LV	CCTV EQUIPMENT			2.00	04/27/2013	CHECKED ALL CONNECTIONS,ALL OK		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S51	UNSCHEDULED SYSTEM INSPECTION	2LVA	CAMERA		CCTV CAMERA (B-CAB)	1.50	04/27/2013	T/S CAMERA, ALL WORKING		86	SUSPECTED FAILURE	CL	CLEANED/WASHED/FUMIGATED	
4478695	4154	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR			0.50	04/25/2013	CAMERA VIEWS SHOW EPB'S		86	SUSPECTED FAILURE	TT	TESTED	R1
4479369	908	A			S23	CCTV/APC/EVENT RECORDER FAILS	222100	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	0.75	06/20/2013	ADJUST CAMERA #2		78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1
	3756	A			S23	CCTV/APC/EVENT RECORDER FAILS	222100	CAMERA		CCTV CAMERA (B-CAB ARTIC AREA)	1.00	04/27/2013	ADJUST CAMERA TO SPEC		78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4479604	3917	P			N30	T-4 PM 9,000 MILE PKG	4LVFE	CAMERA, EXTERIOR			2.00	05/08/2013	ADJUSTED RIGHT CAMERA		78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1
4479722	4096	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT			1.00	04/28/2013	CHECKED VIEW FROM 402 CAB-FINE		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4479723	4096	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT			1.00	04/28/2013	CHECKED VIEW FROM 402 CAB-FINE		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4480276	3860	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/16/2013					IN	INSPECTED	R1
	6501	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.25	05/17/2013					IN	INSPECTED	R1
4480775	5902	A			S08	CARBODY/CAR/CAB INTER FAILURE	2LV	CCTV EQUIPMENT			0.50	01/24/2014	CHECKED BOTH CABS, FINE		69	NO DEFECT FOUND	CK	CHECKED	R1
4482981	5095	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/13/2013					IN	INSPECTED	R1
4483754	4157	A			S52	CCTV DATA PACK/EVENT RECORDER	4LVFE	CAMERA, EXTERIOR			1.00	05/01/2013	ADJ CAMERA UP		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4484614	3340	H			N00	T-1 PM 4,500 MILE PKG	222000	CCTV EQUIPMENT			1.00	05/08/2013	INSTALLED MISSING CONDUIT				IO	INSTALLED ONLY	R1
4485342	3781	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			4.00	06/12/2013	T/S REAR VIEW MONITORS		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	4147	B			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			3.00	05/04/2013	T/S	TIGHTENED LOOSE CONNECTION CHECKED CONNECTION ADI. RE-TEST	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		G			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			2.50	05/04/2013	T/S		57	LOOSE	TS	TROUBLESHOOT	
	5895	B			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			5.50	05/06/2013	PUT IN NEW OMRONS. GOT PICTURE	IN TRAILING CAB, CAR 130B RT HAND MONITOR WILL SOMETIMES DISPLAY PIC. FROM REAR TRAIL-ING CAB.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4485529	4095	B			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	05/14/2013					IN	INSPECTED	R1
4485533	3419	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	05/29/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/29/2013					IN	INSPECTED	R1
4487899	4923	A			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT		CCTV CAMERA (B-CAB)	7.00	05/18/2013	T/S CCTV-NARROWED PROBLEM	DOWN TO LEFT VDA	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	5906	D			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT		CCTV CAMERA (B-CAB)	5.00	05/17/2013	REPAIRS OUT FO CAMERAS		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4487904	5096	G			N20	T-3 PM 4,500 MILE PKG	2LVFG	MOUNTS/HARDWARE			1.00	05/16/2013	R/R DIODE		07	BURNED OUT	RR	REMOVED AND REPLACED	R1
4487907	5094	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	06/01/2013					IN	INSPECTED	R1
	5898	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	06/02/2013					IN	INSPECTED	R1
4488401	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		'B' CAR	1.00	05/09/2013	MONITORS ARE MOUNTED INCORRECT		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4488478	3631	J			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	05/19/2013					IN	INSPECTED	R1
4488933	4095	G			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR			0.50	05/20/2013	R/R CAMERA HOUSING		53	LEAKING/CONDENSATION	RR	REMOVED AND REPLACED	R1
4489148	3917	C			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/14/2013					IN	INSPECTED	R1
		E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/14/2013					IN	INSPECTED	R1
4489151	3828	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	06/04/2013					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			2.00	06/04/2013					IN	INSPECTED	R1
4489736	5091	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			1.50	05/14/2013	RT MONITOR NO REAR DISPLAY	WHEN I SPLIT SCREE ELIMINATED CONTROL BOX MONITOR CAMERA AND111 RX ALSO CLEANED E HEADS MOST LIKEY A SIGNAL FROM COUPLED CAR	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4490361	3631	B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/24/2013					IN	INSPECTED	R1
		C			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/24/2013					IN	INSPECTED	R1
	5095	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			3.00	05/25/2013					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4490999	5093	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	05/24/2013					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	05/24/2013					IN	INSPECTED	
4491451	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT			2.00	05/18/2013	TESTED AS SINGLE IN SHOP. NDF	CAR MOVE	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		C			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT			1.00	05/18/2013	TEST CAR W/CAR 245-WORKS		86	SUSPECTED FAILURE	TT	TESTED	
4491643	4924	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	06/06/2013					IN	INSPECTED	R1
	6501	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	06/06/2013					IN	INSPECTED	R1
	6605	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	06/06/2013					IN	INSPECTED	R1
4492360	3806	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	06/01/2013					IN	INSPECTED	R1
		E			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	06/01/2013					IN	INSPECTED	
4492378	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT			0.75	05/19/2013	111 A RIGHT MONITOR BLUE	SCREEN	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		D			S23	CCTV/APC/EVENT RECORDER FAILS	222460	WIRING/CONNECTIONS			0.25	05/19/2013	SWAPPED COAX CONNECTIONS ON	RX'S DEFECT	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	
		E			S23	CCTV/APC/EVENT RECORDER FAILS	222460	WIRING/CONNECTIONS			0.50	05/19/2013	R/R CABLE FROM CONTROL BOX		86	SUSPECTED FAILURE	RR	REMOVED AND REPLACED	
	5898	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.50	05/19/2013	B END COUPLED, BLUE AND FUZZY	ONLY ON ONE SIDE.	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4493110	2701	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	05/28/2013					IN	INSPECTED	R1
	3340	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/29/2013					IN	INSPECTED	R1
	3395	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	05/31/2013					IN	INSPECTED	R1
4493356	3522	A			S51	UNSCHEDULED SYSTEM INSPECTION	2LV	CCTV EQUIPMENT			0.50	05/22/2013	CHECKED-GOOD		81	SCHEDULED CHANGE/INSTALLATION	CK	CHECKED	R1
4496397	3693	A			A07	MISC - SHOP/YARD/CLEANUP	4LVA1	CAMERA HOUSING			1.25	05/24/2013	CLEANED SIDE VIEW CCTV CAMERA		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4496489	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT		'B' CAR	0.50	05/24/2013	MONITOR OK, CONTROL BOX NEEDS	R/R	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4496740	3632	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	06/10/2013					IN	INSPECTED	R1
		B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	06/10/2013					IN	INSPECTED	
4499713	3631	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	06/18/2013					IN	INSPECTED	R1
	5093	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	06/17/2013					IN	INSPECTED	R1
4502322	3806	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	06/10/2013					IN	INSPECTED	R1
	5095	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	06/10/2013					IN	INSPECTED	R1
4502781	4157	J			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR			1.00	06/11/2013	R/R B-LEFT CAMERA LENS		13	CHIPPED/PITTED	RR	REMOVED AND REPLACED	R1
4503266	4923	G			N10	T-2 PM 4,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	2.00	06/10/2013	T/S CAB MONITOR PROBLEM R/R	SWITCHED MONITORS NO FIX ALSO SWITCHED VDA OUTPUTS TO SWITCH	27	DEFECTIVE	RR	REMOVED AND REPLACED	R1
4503736	2701	A			S10	COMMUNICATION FAILURE	4LVFE	CAMERA, EXTERIOR			0.50	06/04/2013	CLEAN LENSES		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
	5998	A			S10	COMMUNICATION FAILURE	4LVFE	CAMERA, EXTERIOR			0.50	06/04/2013	CLEAN LENSES		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4503803	4157	H			N10	T-2 PM 4,500 MILE PKG	2LVFG	MOUNTS/HARDWARE			0.50	06/13/2013	REPAIR CCTV MONITOR BRKT		03	BENT/PINCHED	RE	REPAIRED	R1
4505679	1209	A			N04	T-1 PM 40,500 MILE PKG	M1312	TEST: CCTV			1.00	06/20/2013					IN	INSPECTED	R1
4505684	3340	A			N22	T-3 PM 13,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (B-CAB)	0.50	06/18/2013	ADJ. CAMERA #4				AJ	ADJUSTED	R1
4505685	3756	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	06/13/2013					IN	INSPECTED	R1
	4095	E			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	06/12/2013					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4505889	3750	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	06/21/2013					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	06/21/2013					IN	INSPECTED	R1
4507044	3669	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	06/27/2013					IN	INSPECTED	R1
	5095	B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	06/26/2013					IN	INSPECTED	R1
4507045	3340	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	06/18/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	06/18/2013					IN	INSPECTED	R1
4509421	5096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	0.75	08/04/2013	PULL DATA PACK,CLEANED CAMERAS	ON 8/4/13 ALL IMAGES SHOWED ON ALL CAMERAS	86	SUSPECTED FAILURE	TT	TESTED	R1
4509557	5899	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	'B' CAR	1.50	06/13/2013	T/S R SIDE REAR VIEW CAMERA	IMAGE OF OTHER SIDE,FOUND WIRING REVERSED TO CONTROL BOXPLACE WIRING IN PROPER SOCKET WORKS FINE NOW	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4510436	4924	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	2.00	06/29/2013					IN	INSPECTED	R1
	5898	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	06/30/2013					IN	INSPECTED	R1
4510737	3806	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	07/08/2013					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/08/2013					IN	INSPECTED	R1
	5095	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	07/08/2013					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/08/2013					IN	INSPECTED	R1
4511143	5906	H			N20	T-3 PM 4,500 MILE PKG	2LVFE	CAMERA	.	.	2.50	06/30/2013	R/R CAMERA #1 RECONNECTED CAM		61	MALFUNCTION/REASON UNKNOWN	RR	REMOVED AND REPLACED	R1
4512324	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	'B' CAR	0.50	06/20/2013	WORKING-		49	INTERMITTENT/FLUCTUATING	IN	INSPECTED	R1
4512428	5093	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	07/05/2013					IN	INSPECTED	R1
4512434	5093	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	06/29/2013					IN	INSPECTED	R1
	5906	B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	06/30/2013					IN	INSPECTED	R1
4512950	3449	G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	07/09/2013					IN	INSPECTED	R1
	4120	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.70	07/08/2013					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	07/08/2013					IN	INSPECTED	R1
4513293	6501	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.	.	2.00	07/11/2013	CLEAN INSIDE AND OUT.		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4513958	5091	B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	07/03/2013					IN	INSPECTED	R1
	5093	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	07/06/2013					IN	INSPECTED	R1
4514414	4923	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT	.	CCTV CAMERA (A-CAB)	5.50	08/26/2013	ADJUSTED CAMERA		86	SUSPECTED FAILURE	AJ	ADJUSTED	R1
	5093	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT	.	.	0.75	08/26/2013	T/S CAMERA SYSTEM-CLEAN GLASS	CHECK DATA PACK FOR BLURRY IMAGE CAMERA 1 A-END OUT OF FOCUS & MIS ALIGN	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4514517	3632	I			N00	T-1 PM 4,500 MILE PKG	222100	CAMERA	.	CCTV RECORDING UNIT	1.00	07/03/2013	TS RED LIGH ON RECORDER		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4515858	3340	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	07/18/2013					IN	INSPECTED	R1
	3790	F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/17/2013					IN	INSPECTED	R1
4516949	5905	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	1.00	06/03/2013	TESTED LT MONITOR DESK, FOUND	BAD CONTROL BOX, NONE IN STORE			TS	TROUBLESHOOT	R1
4519202	3630	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT	.	CCTV DATA PACK	0.25	07/01/2013	R/R DATA PACK		81	SCHEDULED CHANGE/INSTALLATION	RR	REMOVED AND REPLACED	R1
4519502	5091	A			S52	CCTV DATA PACK/EVENT RECORDER	4LVH	RX UNIT	.	.	1.50	07/01/2013	ADJUST 408 LEFT SIDE RECIEVER	TO FIX BLUE IMAGE ON REAR VIEWMONITOR	65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4520163	1209	D			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/14/2013					IN	INSPECTED	R1
	5093	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	07/14/2013					IN	INSPECTED	R1
4520747	4120	D			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	07/16/2013					IN	INSPECTED	R1
	5091	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	07/16/2013					IN	INSPECTED	R1
4522517	3790	A			S52	CCTV DATA PACK/EVENT RECORDER	4LV	CCTV EQUIPMENT	.	EVENT RECORDER ASSEMBLY T2/T3	1.00	07/09/2013	EVENT RECORDER DOWNLOADED		81	SCHEDULED CHANGE/INSTALLATION	DA	DOWNLOADED/ARCHIVED	R1
4522533	5905	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT	.	.	0.50	07/09/2013	TESTED, NO FAULTS				IN	INSPECTED	R1
4522557	3631	B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/21/2013					IN	INSPECTED	R1
	4921	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	07/23/2013					IN	INSPECTED	R1
4523010	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	0.50	07/11/2013	COULDN'T DRIVE IT IN THE YARD	BUT THE MONITOR IS WORKING AT THIS TIME.	86	SUSPECTED FAILURE	IN	INSPECTED	R1
4523147	3630	B			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	07/23/2013					IN	INSPECTED	R1
	3735	C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	07/23/2013					IN	INSPECTED	R1
4523682	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA	.	CCTV CAMERA (B-CAB)	1.00	07/11/2013	TOOK HANDHELD MONITOR, PULLED	DATA PACK AND CHECKED IN SHOP IN CONSISTED PUTUN IN ALL CAMERAS, VARIES ON SUNLIGHT BRIGHTNESS.	86	SUSPECTED FAILURE	IN	INSPECTED	R1
4524247	4147	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	07/29/2013					IN	INSPECTED	R1
	5898	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/26/2013					IN	INSPECTED	R1
4524250	3340	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	07/25/2013					IN	INSPECTED	R1
	5898	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/21/2013					IN	INSPECTED	R1
4524698	3750	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	07/31/2013					IN	INSPECTED	R1
		B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	07/31/2013					IN	INSPECTED	R1
4525429	1209	E			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	07/18/2013					IN	INSPECTED	R1
4525993	5904	E			S10	COMMUNICATION FAILURE	222460	WIRING/CONNECTIONS	.	.	1.00	07/18/2013	R/R ROCKER SWITCH		89	STUCK	RR	REMOVED AND REPLACED	R1
4526082	3419	K			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	08/06/2013					IN	INSPECTED	R1
4526528	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	1.50	07/17/2013	T/S LH MONITOR FOGGY-		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	2.00	07/19/2013	T/S MONITOR		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	
		C			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	0.50	07/19/2013	CAR MOVE		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	
		E			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE1	MOUNT/HOUSING/MIRROR	.	.	0.50	07/19/2013	INSTALLED CAMERA COVER		66	MISSING	IO	INSTALLED ONLY	
	5898	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	5.50	07/19/2013	R/R CAMERA HOUSING WITH SLIGHT IMPROVEMENT, NEEDS MORE T/S		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4526693	3661	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	07/23/2013					IN	INSPECTED	R1
	5902	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	07/22/2013					IN	INSPECTED	R1
4527710	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT	.	.	0.75	07/20/2013	INSP FOUND THAT IT WAS BLUE		86	SUSPECTED FAILURE	IN	INSPECTED	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT	.	.	0.75	07/20/2013	CHECKED THE WIRING, NOT LOOSE	WIRING	86	SUSPECTED FAILURE	CK	CHECKED	
		C			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT	.	.	0.75	07/20/2013	ADJ. KNOB		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	
		D			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT	.	.	0.75	07/20/2013	KEYED DOWN AND BACK UP TO TEST		86	SUSPECTED FAILURE	TT	TESTED	

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4527762	1209	C			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV			1.00	08/04/2013					IN	INSPECTED	R1
		D			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV			1.00	08/04/2013					IN	INSPECTED	
4527992	908	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	08/07/2013					IN	INSPECTED	R1
		B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	08/07/2013					IN	INSPECTED	
4528212	908	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	08/01/2013					IN	INSPECTED	R1
		A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	08/02/2013					IN	INSPECTED	R1
4528561	3913	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			1.50	07/23/2013	R/R RX BOX, WORKING GOOD		27	DEFECTIVE	RR	REMOVED AND REPLACED	R1
4530740	3726	D			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	08/15/2013					IN	INSPECTED	R1
		A			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.70	08/16/2013					IN	INSPECTED	R1
4531742	3750	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	07/30/2013					IN	INSPECTED	R1
		A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	07/30/2013					IN	INSPECTED	R1
4533051	3395	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	08/20/2013					IN	INSPECTED	R1
4537256	5093	D			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV			1.00	08/19/2013					IN	INSPECTED	R1
4537465	3340	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	08/12/2013					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	08/12/2013					IN	INSPECTED	
4537679	4120	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	08/17/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	08/17/2013					IN	INSPECTED	
4537680	5093	C			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	08/23/2013					IN	INSPECTED	R1
		E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	08/23/2013					IN	INSPECTED	
4538030	3860	A			S52	CCTV DATA PACK/EVENT RECORDER	222000	CCTV EQUIPMENT		CCTV RECORDING UNIT	1.00	08/05/2013	T/S CCTV PRO 6000.		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S52	CCTV DATA PACK/EVENT RECORDER	222000	CCTV EQUIPMENT		CCTV RECORDING UNIT	0.50	08/05/2013	R/R PRO 6000		86	SUSPECTED FAILURE	RR	REMOVED AND REPLACED	
4538913	3632	B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	08/20/2013					IN	INSPECTED	R1
		A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	08/19/2013					IN	INSPECTED	R1
4539552	6501	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	08/26/2013					IN	INSPECTED	R1
4540165	4147	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	08/20/2013					IN	INSPECTED	R1
		G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	08/20/2013					IN	INSPECTED	
4540759	5091	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	08/20/2013					IN	INSPECTED	R1
		E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	08/20/2013					IN	INSPECTED	R1
		A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	08/20/2013					IN	INSPECTED	R1
4541005	331	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	08/19/2013					IN	INSPECTED	R1
		G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	08/18/2013					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4541009	4924	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	08/25/2013					IN	INSPECTED	R1
		G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.50	08/25/2013					IN	INSPECTED	
4541675	3726	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.	'A' TRUCK, RIGHT SIDE	0.50	10/02/2013	INSPECTED RIGHT MONITOR HARD-	WARE,FOUND NOTHING BROKEN	05	BROKEN	IN	INSPECTED	R1
	5091	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.	.	0.50	08/12/2013	R/R RIGHT MONITOR BRACKET		05	BROKEN	RR	REMOVED AND REPLACED	R1
4542332	5898	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	08/26/2013					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	08/26/2013					IN	INSPECTED	
4543262	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.	.	0.50	09/25/2013	ADJ. LEFT SIDE CAMERA		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4543398	3607	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	09/01/2013					IN	INSPECTED	R1
		G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	2.00	09/01/2013					IN	INSPECTED	
4543854	5093	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	08/25/2013					IN	INSPECTED	R1
		B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	08/25/2013					IN	INSPECTED	
4543855	5094	G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	08/31/2013					IN	INSPECTED	R1
4544068	4921	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	08/29/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	08/29/2013					IN	INSPECTED	
4544207	1209	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.	.	1.00	08/18/2013	SEARCHED ON LINE & IN MANUALS	COULD NOT FIND ANY INFO ON HOWTO ADJUST CAMERA(SEE ATTACHED)NEEDS A SMARTER MECHANIC	65	MISADJUSTED/MISALIGNED	TS	TROUBLESHOOT	R1
4544270	5899	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	08/29/2013					IN	INSPECTED	R1
	5906	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	08/31/2013					IN	INSPECTED	R1
4544276	4120	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	08/23/2013					IN	INSPECTED	R1
		F			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	08/23/2013					IN	INSPECTED	
4544278	3340	G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	08/31/2013					IN	INSPECTED	R1
	3419	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	08/30/2013					IN	INSPECTED	R1
4544744	5899	B			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	08/27/2013					IN	INSPECTED	R1
		C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	08/27/2013					IN	INSPECTED	
4545866	3595	B			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	2.50	08/22/2013	T/S DARK MONITOR		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4546628	4147	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	09/09/2013					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	09/09/2013					IN	INSPECTED	
4547209	3419	D			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	09/05/2013					IN	INSPECTED	R1
	5898	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	09/06/2013					IN	INSPECTED	R1
4548208	3340	K			N10	T-2 PM 4,500 MILE PKG	2LVFE	CAMERA	.	.	0.50	09/11/2013	R/R CAMERA				RR	REMOVED AND REPLACED	R1
4549378	5902	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	09/08/2013					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	09/08/2013					IN	INSPECTED	
4549382	3632	E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	09/12/2013					IN	INSPECTED	R1
	3669	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	09/16/2013					IN	INSPECTED	R1
4549385	4096	J			N30	T-4 PM 9,000 MILE PKG	4LV	CCTV EQUIPMENT	.	'A' CAR	1.00	08/31/2013	R/R MONITOR BRACKET		05	BROKEN	RR	REMOVED AND REPLACED	R1
4550227	4096	A			S50	CONSIST FAILURE INSPECTION	2LV	CCTV EQUIPMENT	.	'A' CAR	0.80	08/30/2013	TESTED CCTV VIEWS, 123 A RIGHT	MONITOR HAS BLUE, NEED CONTROLBOX R/R'ED	63	MECHANICAL FAILURE	TS	TROUBLESHOOT	R1
4550297	908	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	09/13/2013					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
	3631	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	09/12/2013					IN	INSPECTED	R1
4550300	5895	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	09/08/2013					IN	INSPECTED	R1
		G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	09/08/2013					IN	INSPECTED	
4552833	3756	B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	09/13/2013					IN	INSPECTED	R1
	5095	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	09/12/2013					IN	INSPECTED	R1
4552834	3661	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.75	09/14/2013					IN	INSPECTED	R1
	5899	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	09/20/2013					IN	INSPECTED	R1
4552989	4095	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	09/16/2013					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	09/16/2013					IN	INSPECTED	
4553177	4120	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT	.	.	3.00	09/03/2013	"A" CAB,LEFT MONITOR DARK.	CLEANED ELECTRICAL HEADS(109X 243) TAPPED ON 8A55,WIGGLED ALOT OF WIRES, R&R TOP CONTROLBOX.ATTEMPTED TO ADJUST & CONFIRM MONITOR SETTINGS, BUT NO JOY.NEES FURTHER T/S	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4554155	3419	D			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	09/27/2013					IN	INSPECTED	R1
		H			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	09/27/2013					IN	INSPECTED	
4555623	5095	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	09/23/2013					IN	INSPECTED	R1
4556556	4921	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVA	CAMERA, INTERIOR	.	CCTV CAMERA (B-CAB)	1.50	10/10/2013	VIEWED CAMERAS LIVE ON LAPTOP	ALL GOOD	69	NO DEFECT FOUND	CK	CHECKED	R1
4556573	3522	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.60	09/19/2013					IN	INSPECTED	R1
4558406	3419	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	09/20/2013					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	09/20/2013					IN	INSPECTED	
4558644	3921	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA	.	CCTV CAMERA (B-CAB)	1.00	09/12/2013	WORKED ON CAMERA 4, ADJ. NEEDS	MORE T/S	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	5904	C			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	.	1.50	09/12/2013	T/S		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	6501	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	CCTV RECORDING UNIT	6.50	09/12/2013	CLEANED CCTV PLUGS, NEEDS ADJ.		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT	.	CCTV RECORDING UNIT	1.25	09/13/2013	CHECKED ALL GOOD,LOOSE/TIGHTEN		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	
4559283	4096	A			S07	CAB ELECTRIC CONTROLS	4LV	CCTV EQUIPMENT	.	.	0.50	09/13/2013	DIGITAL RECORDER IS WORKING		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4559339	5899	B			N00	T-1 PM 4,500 MILE PKG	222100	CAMERA	.	CCTV CAMERA (B-CAB)	1.50	10/04/2013	OPEN'BCAMERA & CLEAN		27	DEFECTIVE	CL	CLEANED/WASHED/FUMIGATED	R1
4559545	3924	K			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.75	09/25/2013					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4560254	4096	D			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	10/12/2013					IN	INSPECTED	R1
	4147	H			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	10/08/2013					IN	INSPECTED	R1
4561393	1209	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	09/30/2013					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	10/01/2013					IN	INSPECTED	
4562814	3449	H			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	10/02/2013					IN	INSPECTED	R1
4562933	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT		'A' CAR	0.50	09/21/2013	LOOKS GOOD, NDF		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4564020	5899	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB)	0.50	09/25/2013	ADJUST CAMERA		78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (FORWARD FACING)	0.50	09/25/2013	ADJUST CAMERA		78	OUT OF SPECIFICATION	AJ	ADJUSTED	
4564463	4154	A			S10	COMMUNICATION FAILURE	4LVH	RX UNIT			1.00	09/24/2013	ADJ. RECEIVE TO CLEAR PICTURE		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4564942	4120	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVA	CAMERA		CCTV CAMERA (B-CAB ARTIC AREA)	1.00	09/25/2013	CAMERA 3 ON B-END INVESTIGATED	LENS HAD SERIOUS AMOUNTS OF GOOEY BUBBLE GUM, CLEANED, VIEW EACH ONE FOR CLARITY OK.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4564943	3749	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVA	CAMERA		CCTV CAMERA (B-CAB ARTIC AREA)	1.50	10/01/2013	VERIFIED CAMERA 3 WAS NOT	GIVING A PICTURE, CHECK CAMERA WITH TEST UNIT, FOUND COAX WAS CONNECTED TO WRONG JACK ON CAMERA CONNECTED INTO THE CORRECT JACK. NOW THERE IS A PICTURE	33	DISCONNECTED/DISENGAGED-ELECTR	RE	REPAIRED	R1
	4120	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVA	CAMERA		CCTV CAMERA (B-CAB ARTIC AREA)	1.50	09/25/2013	INVESTIGATED CAMERA 3 DARK PIC	TURE TIGHTENED WIRE LOOSE ON BACK OF CAMERA, MOVED COAXIAL TO PROPER CONNECTION PORT. ACHIEVED IMAGE STILL GRAINY. SWAPPED CAMERA NO CHANGE, DEFECT COULD BE CANON PLUG FURTHER T/S NEEDED	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4564965	4921	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFG	MOUNTS/HARDWARE		'A' CAR	0.25	09/25/2013	TIGHTENED BOLT ON MOUNTING	BRACKET.	57	LOOSE	TI	TIGHTENED	R1
4565541	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.50	09/26/2013	WORKING		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4565545	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.50	09/26/2013	REAR VIEW 1/4 SCREEN, NEEDS T/S		61	MALFUNCTION/REASON UNKNOWN	IN	INSPECTED	R1
4566386	4096	G			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			1.00	10/11/2013	TIGHTEN ALL MONITOR/HARDWARE		57	LOOSE	TI	TIGHTENED	R1
4566406	4147	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	10/13/2013					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	10/13/2013					IN	INSPECTED	
4566645	4120	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	10/10/2013					IN	INSPECTED	R1
4566825	5094	A			S10	COMMUNICATION FAILURE	4LV	CCTV EQUIPMENT			0.50	09/29/2013	CHECKED ROAD RECORDER FOR	STEADY GREEN LIGHT AND FLASHINRED, CHECKED OK	69	NO DEFECT FOUND	CK	CHECKED	R1
4571555	3607	D			N10	T-2 PM 4,500 MILE PKG	2LVFE	CAMERA		'A' CAR	1.00	10/08/2013	RESET CCTV CAMERA				RV	RESET/REBOOTED	R1
		E			N10	T-2 PM 4,500 MILE PKG	2LVFE	CAMERA		'A' CAR	3.00	10/08/2013	T/S CCTV CAMERA SYSTEM		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	
4572667	4095	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	10/13/2013					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	10/13/2013					IN	INSPECTED	
4572891	1209	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	10/28/2013					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	10/30/2013					IN	INSPECTED	
4573941	3860	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		CCTV CAMERA (A-CAB)	1.00	10/08/2013	T/S A RT, MONITOR AT THIS, OK		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4574797	4154	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			1.00	10/09/2013	ADJ. MONITOR TO BEST PICTURE	POSSIBLE	78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1
	4157	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			0.20	11/19/2013	ADJ LEFT RX		71	OUTPUT IMPROPER	AJ	ADJUSTED	R1
4575505	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.50	10/10/2013	CHECKED WORKING		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4575514	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.50	10/10/2013	CLEANED EXTERNAL CAMERA MOUNTS		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4575561	3661	A			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			1.50	10/19/2013	FOUND BAD ZENNER DIODE		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
	3669	H			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			1.00	10/18/2013	T/S CCTV DEFECT		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4576096	4157	A			S10	COMMUNICATION FAILURE	4LVH	RX UNIT			0.20	11/19/2013	ADJ LEFT REC.		71	OUTPUT IMPROPER	AJ	ADJUSTED	R1
4576384	4157	A			N30	T-4 PM 9,000 MILE PKG	4LVFE1	MOUNT/HOUSING/MIRROR			1.00	10/23/2013	R/R SIDE VIEW LENSES	LAPTOP TO UPLOAD FIRMWARE	82	SCRATCHED	RR	REMOVED AND REPLACED	R1
4576830	3828	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	11/06/2013					IN	INSPECTED	R1
	4147	G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	11/03/2013					IN	INSPECTED	R1
4577469	3631	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	10/25/2013					IN	INSPECTED	R1
4578916	3340	G			N10	T-2 PM 4,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	0.50	10/28/2013	ADJ. OUTSIDE CAMERA				AJ	ADJUSTED	R1
4579283	3632	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT			3.00	10/18/2013	T/S CCTV MALFUNCTION-FOUND	CAMERA-3 WITH NO PICTURE, FOUND NO PWOER AT CAMERA-3 NEED NEW CAMERA.	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	222100	CAMERA		CCTV CAMERA (B-CAB ARTIC AREA)	1.00	10/18/2013	REPAIRED LOOSE CONNECTION-MAY				RE	REPAIRED	
4579575	3272	E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	12/15/2013					IN	INSPECTED	R1
	3756	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.25	12/17/2013					IN	INSPECTED	R1
4580317	5902	K			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	11/02/2013					IN	INSPECTED	R1
4580346	4157	B			N30	T-4 PM 9,000 MILE PKG	4LVFE1	MOUNT/HOUSING/MIRROR			0.50	10/23/2013	R/R LENSES		87	SOLDERED	TT	TESTED	R1
	4923	B			N30	T-4 PM 9,000 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB ARTIC AREA)	1.00	10/31/2013	ADJUSTED CAMERA		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
		C			N30	T-4 PM 9,000 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (B-CAB ARTIC AREA)	1.00	10/31/2013	ADJUSTED CAMERA		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	
4580879	3909	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	11/04/2013					IN	INSPECTED	R1
	5096	C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	11/04/2013					IN	INSPECTED	R1
4582120	3419	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	11/27/2013					IN	INSPECTED	R1
	5905	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	11/28/2013					IN	INSPECTED	R1
4582681	4157	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			0.20	11/19/2013	ADJ LEFT RX		71	OUTPUT IMPROPER	AJ	ADJUSTED	R1
4584116	3750	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			3.00	10/31/2013	ADJUST FOCUS ON CAMERA'S ALL	HAVE GOOD IMAGE NOW AFTER VIEWING DATA PACK	61	MALFUNCTION/REASON UNKNOWN	AJ	ADJUSTED	R1
	3909	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVA	CAMERA		CCTV CAMERA (B-CAB ARTIC AREA)	0.25	10/29/2013	INSPECTED CAMS. W/CCTV TESTED	ALL SHOWED GOOD.	61	MALFUNCTION/REASON UNKNOWN	TT	TESTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
	5096	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			3.50	10/30/2013	CLEANED DATA PACK,FOUND CAMERA	4 VERY DISTORTED, CLEANED COAX AT DVR,IMAGE STILL POOR,CHANGE COAX PLUG AT DVR	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4584214	5096	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	11/10/2013					IN	INSPECTED	R1
4584757	3631	E			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	11/06/2013					IN	INSPECTED	R1
	5091	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	11/06/2013					IN	INSPECTED	R1
4587922	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFG	MOUNTS/HARDWARE			0.75	11/02/2013	CHECKED IT WAS OFF		86	SUSPECTED FAILURE	CK	CHECKED	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFG	MOUNTS/HARDWARE			0.75	11/02/2013	FOUND NEW BRACKET		27	DEFECTIVE	GP	GET PARTS	
		C			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFG	MOUNTS/HARDWARE			0.75	11/02/2013	R/R BRACKET		27	DEFECTIVE	RR	REMOVED AND REPLACED	
4587956	3756	K			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	11/13/2013					IN	INSPECTED	R1
4587959	1209	C			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	11/19/2013					IN	INSPECTED	R1
		E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	11/19/2013					IN	INSPECTED	
4587962	1209	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	11/20/2013					IN	INSPECTED	R1
		F			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	11/20/2013					IN	INSPECTED	
4588184	3631	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	11/27/2013					IN	INSPECTED	R1
		B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	11/27/2013					IN	INSPECTED	
4589011	2701	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	11/21/2013					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	11/21/2013					IN	INSPECTED	
4590339	3756	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	11/21/2013					IN	INSPECTED	R1
		B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	11/21/2013					IN	INSPECTED	
4590342	3631	C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	11/12/2013					IN	INSPECTED	R1
	3735	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	11/17/2013					IN	INSPECTED	R1
4591086	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			3.00	11/08/2013	T/S B CAB R MONITOR SHOWS	NUMBERS, R/R RECIEVER 8N2 TESTED AND R/R COAXIAL, TESTEDCONTROL BOX, WORKING	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4591164	3632	E			N30	T-4 PM 9,000 MILE PKG	4LVA	CAMERA, INTERIOR		CCTV CAMERA (A-CAB)	2.50	11/19/2013	T/S CAB CAMERA-NO LUCK		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4591629	5096	H			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			0.50	11/20/2013	B-CAB MONITOR WORKED FINE		86	SUSPECTED FAILURE	TT	TESTED	R1
4591634	2701	A			N30	T-4 PM 9,000 MILE PKG	4LVFE	CAMERA, EXTERIOR			0.75	11/17/2013	ADI CAMERA ANGLE LEFT SIDE		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4591807	5899	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		'B' CAR	0.50	11/08/2013	T/S MONITOR-DARK RESET WORKS	FINE	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4592063	4147	K			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.75	11/18/2013					IN	INSPECTED	R1
4592479	5096	B			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	12/01/2013					IN	INSPECTED	R1
		C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	12/01/2013					IN	INSPECTED	
4593185	3917	K			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	12/04/2013					IN	INSPECTED	R1
4593187	3340	E			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.00	11/20/2013					IN	INSPECTED	R1
4593188	3726	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	12/01/2013					IN	INSPECTED	R1
	3911	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	11/29/2013					IN	INSPECTED	R1
4593746	3449	A			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	11/19/2013					IN	INSPECTED	R1
	3630	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			3.00	11/18/2013					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4596272	5898	A			S10	COMMUNICATION FAILURE	2LVA	CAMERA		CCTV CAMERA (B-CAB ARTIC AREA)	1.00	12/26/2013	T/S REAR VIEW CAMERA NOT IMAGING RESET DVR FOR PROPER AMMOUNT OF CAMERAS,CHECK ALL SIMAGES		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4596638	3693	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFG	MOUNTS/HARDWARE			1.00	11/20/2013	R/R HOUSING WINDOW		82	SCRATCHED	RR	REMOVED AND REPLACED	R1
4596912	4096	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/01/2013					IN	INSPECTED	R1
	4147	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/01/2013					IN	INSPECTED	R1
4597736	4096	A			S19	VANDALISM	2LV	CCTV EQUIPMENT		'B' CAR	0.50	11/21/2013	CARDBOARD IN SWITCH/REMOVED		86	SUSPECTED FAILURE	TT	TESTED	R1
4597815	3340	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/05/2013					IN	INSPECTED	R1
		G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			6.50	12/05/2013					IN	INSPECTED	
	6951	G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			2.00	12/09/2013					IN	INSPECTED	R1
4598269	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			1.00	11/22/2013	TESTED, BOTH ARE GOOD		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4598582	3340	I			N20	T-3 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			3.00	12/06/2013	RR CAMERA 3 ADJ				RR	REMOVED AND REPLACED	R1
4600163	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.50	12/02/2013	T/S CAMERAS 2/3 INTERIOR FOR	GRAINY NASTY QUALITY.	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		B			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	1.00	12/02/2013	R/R CAMERA 2 TEST/ADJ.		71	OUTPUT IMPROPER	RR	REMOVED AND REPLACED	
		C			S23	CCTV/APC/EVENT RECORDER FAILS	2LVA	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	1.00	12/02/2013	R/R CAMERA 3 TEST/ADJ.		71	OUTPUT IMPROPER	RR	REMOVED AND REPLACED	
		E			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.50	12/02/2013	INSTLL DP/TEST OK				TT	TESTED	
4600397	3749	A			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/09/2013					IN	INSPECTED	R1
	3750	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/09/2013					IN	INSPECTED	R1
4600402	3631	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/17/2013					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	12/17/2013					IN	INSPECTED	
4603418	3750	D			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/13/2013					IN	INSPECTED	R1
	5098	A			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/14/2013					IN	INSPECTED	R1
4604575	4147	A			TH7	T2 CCTV DVR SHUTDOWN SET 11/13	2LV	CCTV EQUIPMENT			0.75	12/31/2013	ADJ DVR SETTINGS		81	SCHEDULED CHANGE/INSTALLATION	AJ	ADJUSTED	R1
4604643	5902	A			F45	T4 CCTV DVR SHUTDOWN SET 11/13	4LV	CCTV EQUIPMENT			0.50	12/05/2013	CHECKED, LOOKS GOOD		86	SUSPECTED FAILURE	CK	CHECKED	R1
4605154	4154	A			S19	VANDALISM	2LV	CCTV EQUIPMENT		'A' CAR	0.50	12/04/2013	DEFECT CAUSED BY CARDBOARD	JAMMED INTO CONSOLE SWITCH	96	VANDALISM	RO	REMOVED ONLY	R1
4606555	4924	O			N30	T-4 PM 9,000 MILE PKG	4LVFE	CAMERA, EXTERIOR			1.00	12/19/2013	ADJ CAMERA VIEW LEFT SIDE		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4606756	4147	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/21/2013					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	12/21/2013					IN	INSPECTED	
4606760	3340	A			N20	T-3 PM 4,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (A-CAB)	1.00	12/17/2013	R/R CAMERA #4				RR	REMOVED AND REPLACED	R1
		B			N20	T-3 PM 4,500 MILE PKG	2LVA	CAMERA		CCTV CAMERA (A-CAB)	0.50	12/17/2013	ADJ CAMERA #1				AJ	ADJUSTED	
4606943	3750	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	12/18/2013					IN	INSPECTED	R1
	3911	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/17/2013					IN	INSPECTED	R1
4608211	3911	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	01/05/2014					IN	INSPECTED	R1
	5899	A			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/04/2014					IN	INSPECTED	R1
4608213	3340	O			N30	T-4 PM 9,000 MILE PKG	4LVFE1	MOUNT/HOUSING/MIRROR			1.00	12/18/2013	RR CAMERA COVER/ADJ				RR	REMOVED AND REPLACED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
		P			N30	T-4 PM 9,000 MILE PKG	4LVFE1	MOUNT/HOUSING/MIRROR			1.00	12/18/2013	REPAIRED CAMERA COVER				RA	REASSEMBLED/RECONNECTED	
4608862	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT			0.50	09/26/2013	CLN COUPLER INSP DISTORTED	VIEW NEEDS MORE TS RIGHT REAR VIEW ONLY	61	MALFUNCTION/REASON UNKNOWN	IN	INSPECTED	R1
4608863	5895	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			1.00	10/12/2013	LEFT CAMERA IS FUZZY WHEN ON	SPLIT SCREEN FOR REAR VIEW NEEDS MORE T/SHOOT	86	SUSPECTED FAILURE	IN	INSPECTED	R1
4608941	6501	F			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT		'B' CAR	1.00	12/20/2013	T/S, MONITOR RIGHTSIDE B END		27	DEFECTIVE	TS	TROUBLESHOOT	R1
4609525	3924	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	12/29/2013					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	12/29/2013					IN	INSPECTED	
4610179	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.75	12/14/2013	ADJ. SETTINGS		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
	5895	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.75	12/14/2013	ADJ. SETTINGS		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4610272	3449	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/02/2014					IN	INSPECTED	R1
		E			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/02/2014					IN	INSPECTED	
4611454	3909	A			S52	CCTV DATA PACK/EVENT RECORDER	4LVFE1	MOUNT/HOUSING/MIRROR			0.50	12/17/2013	CHECK MONITOR/FOUND THAT GLARE	FROM STREET LAMPS, WIPED OFF LENS, BUT WHITE STILL THERE	86	SUSPECTED FAILURE	CL	CLEANED/WASHED/FUMIGATED	R1
4611475	5902	A			S10	COMMUNICATION FAILURE	2LVFE1	MOUNT/HOUSING/MIRROR			0.50	01/04/2014	CLN HOUSING FROM CARBON DUST		31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4612662	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			0.14	12/19/2013	IF DOOR ARE CLOSED/MONITOR	GOES TO FULL VIEW	86	SUSPECTED FAILURE	IN	INSPECTED	R1
4613084	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		'B' CAR	0.50	12/20/2013	CONSOLE SW CARD BOARD FAULT	CARDBOARD STUCK IN SW	19	CRUSHED/DESTROYED	IN	INSPECTED	R1
4613085	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		'B' CAR	1.50	12/20/2013	NEED TO BE SHOP REPAIR		61	MALFUNCTION/REASON UNKNOWN	IN	INSPECTED	R1
	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.00	12/21/2013	FOUND BOTH MONITORS B END DARK	BOTH RED FUSES ON PIGTAILS BADREPLACED	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		C			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS			0.75	12/21/2013	RE-DRILLED LID TO NEW CONTROL	BOX, RE-WIRING	78	OUT OF SPECIFICATION	MO	MODIFIED	
	5895	B			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT		'B' CAR	1.50	12/20/2013	NEED TO BE SHOP REPAIR		61	MALFUNCTION/REASON UNKNOWN	IN	INSPECTED	R1
4613092	4096	A			S19	VANDALISM	2LV	CCTV EQUIPMENT		'B' CAR	0.50	12/20/2013	CARDBOARD IN CONSOLE SW MAL	FUNCTION WORKING	19	CRUSHED/DESTROYED	IN	INSPECTED	R1
4614421	4921	H			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR		'A' TRUCK, LEFT SIDE	0.50	01/03/2014	RR A LEFT CAMERA COVER		82	SCRATCHED	RR	REMOVED AND REPLACED	R1
4614427	3669	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/13/2014					IN	INSPECTED	R1
	3911	A			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/12/2014					IN	INSPECTED	R1
4614692	3449	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			3.00	12/27/2013	TEST/FOUND CAMERA INPUTS OK	DATA PACKS, FOUND THEY WERE CORRUPT	61	MALFUNCTION/REASON UNKNOWN	TT	TESTED	R1
		C			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.00	12/27/2013	TT AGAIN ON LAPTOP COULD SEE	CAMEAR 5 FROM EITHER LEAD CABLE			TT	TESTED	
	3911	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LV	CCTV EQUIPMENT			1.00	12/28/2013	INSPECT				IN	INSPECTED	R1
4616126	5095	C			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT		'B' TRUCK, LEFT SIDE	2.00	01/10/2014	T/S CAMERA PROBLEM TO BAD LENS		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
		D			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR		'B' TRUCK, LEFT SIDE	0.50	01/10/2014	R/R B-RIGHT CAMERA WINDOW		14	CONDEMNED	RR	REMOVED AND REPLACED	
4616128	5898	D			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/07/2014					IN	INSPECTED	R1
		H			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/07/2014					IN	INSPECTED	
4616318	6501	A			S23	CCTV/APC/EVENT RECORDER FAILS	222460	WIRING/CONNECTIONS			4.00	12/30/2013	TS FOUND THE 8K1-34 END OF THE	8K1-71478K1-34 WIRE WAS MISS WIRED TO TERMINAL REMOVED AND PLACED IT TERMINAL 34 OF THE 8K1 RELAY	27	DEFECTIVE	TS	TROUBLESHOOT	R1
4618717	5096	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			1.50	01/15/2014					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4618718	1209	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/12/2014					IN	INSPECTED	R1
	3449	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/12/2014					IN	INSPECTED	R1
4618721	4147	K			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			1.25	01/18/2014	T/S CAMERA		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4618723	4147	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	01/12/2014					IN	INSPECTED	R1
		B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	01/12/2014					IN	INSPECTED	
4619395	5091	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVH	RX UNIT			2.00	01/03/2014	THE RX NEEDS TO BE R/R.	COULD NOT BE FIXED NO PARTS.	35	ELECTRICAL FAILURE	RR	REMOVED AND REPLACED	R1
4619463	3735	D			N10	T-2 PM 4,500 MILE PKG	2LVFE1	MOUNT/HOUSING/MIRROR			1.00	01/10/2014	INSTALL NEW GASKET BOTH COVER	AND HOUSING	53	LEAKING/CONDENSATION	SL	SEALED	R1
4619464	3419	G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/29/2014					IN	INSPECTED	R1
	4147	G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/25/2014					IN	INSPECTED	R1
	4924	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/28/2014					IN	INSPECTED	R1
4619896	4157	B			N00	T-1 PM 4,500 MILE PKG	222150	CAMERA HOUSING		CCTV CAMERA (B-CAB ARTIC AREA)	2.00	01/12/2014	CAMERA HOUSING LENS		05	BROKEN	RR	REMOVED AND REPLACED	R1
4620289	1209	D			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	01/21/2014					IN	INSPECTED	R1
4621969	5095	I			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT			1.50	01/19/2014	T/S DARK MONITOR		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4621974	3632	B			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.50	01/13/2014					IN	INSPECTED	R1
		E			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/13/2014					IN	INSPECTED	
4622526	4096	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT			0.50	01/10/2014	T/S NDF		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4623177	3911	C			N00	T-1 PM 4,500 MILE PKG	222000	CCTV EQUIPMENT			1.50	01/27/2014	CHECK AIMING B-CAB CAM				CK	CHECKED	R1
4623308	5096	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFG	MOUNTS/HARDWARE			1.00	01/11/2014	R/R MONITOR BRACKET		05	BROKEN	RR	REMOVED AND REPLACED	R1
4624836	3449	A			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/22/2014					IN	INSPECTED	R1
	3917	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/21/2014					IN	INSPECTED	R1
4624985	3750	A			S23	CCTV/APC/EVENT RECORDER FAILS	222100	CAMERA		CCTV CAMERA (A-CAB ARTIC AREA)	1.00	01/15/2014	CHECK CAMERA WITH TESTER AT	CAMERA AND RECORDING UNIT ALL LOOKS GOOD VIEWED DATA PACK RECORDING LOOKS GOOD	61	MALFUNCTION/REASON UNKNOWN	IN	INSPECTED	R1
4626478	3750	C			S23	CCTV/APC/EVENT RECORDER FAILS	222460	WIRING/CONNECTIONS			2.00	01/18/2014	R/R CONNECTING CABLE		57	LOOSE	RR	REMOVED AND REPLACED	R1
		D			S23	CCTV/APC/EVENT RECORDER FAILS	222460	WIRING/CONNECTIONS			0.50	01/18/2014	R/R FUSE		07	BURNED OUT	RR	REMOVED AND REPLACED	
4626506	5098	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	02/01/2014					IN	INSPECTED	R1
4626736	5096	C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/21/2014					IN	INSPECTED	R1
		A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	01/22/2014					IN	INSPECTED	
4626849	3340	D			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFF	WIRING/CONNECTIONS			0.50	01/24/2014	REPAIR COUX TERMINAL				RE	REPAIRED	R1
4626864	4147	A			S52	CCTV DATA PACK/EVENT RECORDER	2LV	CCTV EQUIPMENT			0.25	02/18/2014	INSP. B RT MONITOR, WORKING		86	SUSPECTED FAILURE	IN	INSPECTED	R1
4627239	1209	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.50	01/22/2014					IN	INSPECTED	R1
4627270	3669	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	01/27/2014					IN	INSPECTED	R1
	4157	B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	01/27/2014					IN	INSPECTED	R1
4627431	3605	A			S51	UNSCHEDULED SYSTEM INSPECTION	222000	CCTV EQUIPMENT			1.00	01/21/2014	RESET/TEST- NO GOOD		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4627432	3921	C			S16	PROPULSION FAILURE	222000	CCTV EQUIPMENT			6.50	01/22/2014	T/S LS DARK MONITORS		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4627802	5095	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/15/2014					IN	INSPECTED	R1
		G			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/15/2014					IN	INSPECTED	
4627803	3700	D			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	01/31/2014					IN	INSPECTED	R1
	4157	B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	01/30/2014					IN	INSPECTED	R1
4628319	331	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	02/07/2014					IN	INSPECTED	R1
	4159	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/08/2014					IN	INSPECTED	R1
4629541	3340	D			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/13/2014					IN	INSPECTED	R1
		H			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	02/13/2014					IN	INSPECTED	
4629739	3756	C			X03	WHEEL TRUING - FOR WEAR	MIL197	EVENT RECORDER			0.50	02/11/2014					IN	INSPECTED	R1
		F			X03	WHEEL TRUING - FOR WEAR	MIL211	CCTV TEST			0.50	02/11/2014					IN	INSPECTED	
4629953	1209	E			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV			0.50	02/19/2014					IN	INSPECTED	R1
4629963	4147	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	02/17/2014					IN	INSPECTED	R1
		E			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	02/17/2014					IN	INSPECTED	
4629964	3340	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	02/17/2014					IN	INSPECTED	R1
		B			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	02/17/2014					IN	INSPECTED	
4630582	3750	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/08/2014					IN	INSPECTED	R1
		C			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/08/2014					IN	INSPECTED	
4630846	4154	A			S23	CCTV/APC/EVENT RECORDER FAILS	2LVFG	MOUNTS/HARDWARE			1.00	01/28/2014	LOOSE WIRE TERMINAL, SECURED		57	LOOSE	SC	SECURED	R1
4630961	3449	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.50	02/06/2014					IN	INSPECTED	R1
	3750	E			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/05/2014					IN	INSPECTED	R1
4631609	3340	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	02/11/2014					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	02/11/2014					IN	INSPECTED	
4634887	3693	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	02/20/2014					IN	INSPECTED	R1
4634891	3419	H			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/14/2014					IN	INSPECTED	R1
	3595	D			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	02/10/2014					IN	INSPECTED	R1
4635488	3632	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	02/06/2014					IN	INSPECTED	R1
		F			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	02/06/2014					IN	INSPECTED	
4635489	4147	D			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	02/14/2014					IN	INSPECTED	R1
		H			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	02/14/2014					IN	INSPECTED	
4636561	5904	A			S52	CCTV DATA PACK/EVENT RECORDER	2LVFF	WIRING/CONNECTIONS			1.00	02/05/2014	CHECK B-CAB MONITOR, COAX CABLE	TO RECIEVER WAS PULLED TIGHT RECONNECTED WORKED FINE.	03	BENT/PINCHED	AJ	ADJUSTED	R1
4636835	5096	A			N04	T-1 PM 40,500 MILE PKG	M312	TEST: CCTV			0.75	02/12/2014					IN	INSPECTED	R1
4637236	1209	F			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT	'A' CAR		1.00	02/17/2014	T/S LEFT MONITOR DEFECT		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
	5904	I			N10	T-2 PM 4,500 MILE PKG	2LV	CCTV EQUIPMENT	'A' CAR		1.50	02/17/2014	T/S LEFT MONITOR REARVIEW		86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1
4639935	3631	D			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	03/04/2014					IN	INSPECTED	R1
	3756	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/03/2014					IN	INSPECTED	R1
4639937	4157	J			N20	T-3 PM 4,500 MILE PKG	2LVE	CAMERA			1.00	02/19/2014	R/R CAMERA COVER		53	LEAKING/CONDENSATION	RR	REMOVED AND REPLACED	R1
4641106	5895	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.50	02/14/2014	ADJ. IMAGE CAME IN		86	SUSPECTED FAILURE	AJ	ADJUSTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4641108	5895	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.50	02/14/2014	ADJ. IMAGE CAME BACK IN		86	SUSPECTED FAILURE	AJ	ADJUSTED	R1
4641186	3632	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/04/2014					IN	INSPECTED	R1
	3661	D			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	03/03/2014					IN	INSPECTED	R1
4641380	3749	B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	02/24/2014					IN	INSPECTED	R1
	3756	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	02/25/2014					IN	INSPECTED	R1
4642255	3924	B			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/12/2014					IN	INSPECTED	R1
4644172	3661	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV			0.75	03/19/2014					IN	INSPECTED	R1
4644176	3607	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	03/15/2014					IN	INSPECTED	R1
	4924	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/16/2014					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/16/2014					IN	INSPECTED	R1
4645627	3340	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/05/2014					IN	INSPECTED	R1
		G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	03/05/2014					IN	INSPECTED	R1
4646264	1209	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/13/2014					IN	INSPECTED	R1
	3750	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	03/13/2014					IN	INSPECTED	R1
4646999	3924	A			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.25	03/24/2014					IN	INSPECTED	R1
		D			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/24/2014					IN	INSPECTED	R1
4647563	5905	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.50	02/27/2014	TESTED BOTH MONITORS WORKING	GOOD IA ALL SETTINGS FRONT/BACK/AUTO SPLIT SCREEN COULDNTGET TO FAIL			TT	TESTED	R1
4650371	3669	D			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/18/2014					IN	INSPECTED	R1
	3909	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	03/16/2014					IN	INSPECTED	R1
4650808	6501	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			2.00	03/17/2014					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	03/17/2014					IN	INSPECTED	R1
4652000	4096	P			N30	T-4 PM 9,000 MILE PKG	4LV	CCTV EQUIPMENT			1.00	03/17/2014	ADJ. CCTV R MONITOR		65	MISADJUSTED/MISALIGNED	AJ	ADJUSTED	R1
4652643	4147	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	03/20/2014					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	03/20/2014					IN	INSPECTED	R1
4654553	3632	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/25/2014					IN	INSPECTED	R1
	5098	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.50	03/30/2014					IN	INSPECTED	R1
4654556	3395	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	03/21/2014					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	03/21/2014					IN	INSPECTED	R1
4654985	3913	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR			0.50	03/11/2014	CHECKED EXTERIOR CAMERA LENS'S	DID NOT FIND ANY PAINT - DID CLEAN LENS	86	SUSPECTED FAILURE	CL	CLEANED/WASHED/FUMIGATED	R1
4656143	5905	C			S10	COMMUNICATION FAILURE	222000	CCTV EQUIPMENT			0.25	03/13/2014	CCTV WORKS FINE COUPLED TO A	TYPE 3 NO CCTV FOR REAR TO SEE			TS	TROUBLESHOOT	R1
4656730	4921	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.50	03/14/2014	DVR INTERFACE IN PARLOR CAB IS	MISSING THIS CODE COMES UP ON TOD & WILL CONTINUE UNTIL THE INTERFACE IS REPLACED THE RECORDER STILL WORKS	86	SUSPECTED FAILURE	CK	CHECKED	R1
4657037	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT			0.75	03/16/2014	RIGHT SIDE MONITOR DARK CHECK	ALL CONNECTIONS @ MONITOR, CONTROL BOX & VDA CHECKED WIRING @ APPARATUS RACK ALL OKTRIED SWAPPING MONITOR NO LUCKTRIED SWAPPIN VDA NO LUCK. TRIED SWAPPING CONTROL BOX CONTROL BOX WAS THE ISSUE	86	SUSPECTED FAILURE	TS	TROUBLESHOOT	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4657861	5091	A			S52	CCTV DATA PACK/EVENT RECORDER	ZLV	CCTV EQUIPMENT			1.00	03/17/2014	ADJUSTED RX AND TX IN BOTH CAR	CHECK CONTROL BOXES & MONITOR SETTINGS,DIRTY ELEC HEAD CONTACTS	31	DIRTY	CL	CLEANED/WASHED/FUMIGATED	R1
4658464	3913	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFF	WIRING/CONNECTIONS			0.50	03/18/2014	T/S FOUND BAD CONNECTION AT	TERMINAL BOARD- RH MONITOR IS WORKING	33	DISCONNECTED/DISENGAGED-ELECTR	TS	TROUBLESHOOT	R1
4658637	3661	A			N04	T-1 PM 40,500 MILE PKG	MIL312	TEST: CCTV			0.75	03/28/2014					IN	INSPECTED	R1
4660908	3661	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/03/2014					IN	INSPECTED	R1
	3924	B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/03/2014					IN	INSPECTED	R1
4660912	5094	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/11/2014					IN	INSPECTED	R1
	5906	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/14/2014					IN	INSPECTED	R1
4661541	3750	C			N32	T-4 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/06/2014					IN	INSPECTED	R1
	4095	A			N32	T-4 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/06/2014					IN	INSPECTED	R1
4661993	5095	A			N04	T-1 PM 40,500 MILE PKG	MIL312	TEST: CCTV			1.00	03/30/2014					IN	INSPECTED	R1
4661997	3632	B			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/03/2014					IN	INSPECTED	R1
		C			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			1.00	04/03/2014					IN	INSPECTED	R1
4662001	5096	B			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	04/02/2014					IN	INSPECTED	R1
		D			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	04/02/2014					IN	INSPECTED	R1
4662229	5098	I			N00	T-1 PM 4,500 MILE PKG	222100	CAMERA		CCTV CAMERA (B-CAB)	1.00	04/02/2014	ADJUST TO SPEC		78	OUT OF SPECIFICATION	AJ	ADJUSTED	R1
4662339	5094	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR			0.50	03/23/2014	CLEANED EXTERIOR CAMERA LENS		86	SUSPECTED FAILURE	CK	CHECKED	R1
4662450	4096	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/03/2014					IN	INSPECTED	R1
	5906	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	04/04/2014					IN	INSPECTED	R1
4662456	3395	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/12/2014					IN	INSPECTED	R1
	4152	C			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/05/2014					IN	INSPECTED	R1
4663047	4147	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	04/02/2014					IN	INSPECTED	R1
	5898	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/09/2014					IN	INSPECTED	R1
4663732	3828	E			N10	T-2 PM 4,500 MILE PKG	ZLV	CCTV EQUIPMENT		'A' CAR	1.25	04/16/2014	T/S SIDEVIEW CCTV		61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4663754	3661	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/12/2014					IN	INSPECTED	R1
		G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/12/2014					IN	INSPECTED	R1
4665018	3735	J			N00	T-1 PM 4,500 MILE PKG	222150	CAMERA HOUSING		CCTV CAMERA (A-CAB ARTIC AREA)	1.50	04/08/2014	T/S NO HEATER A SIDE VIEW CCTV		93	WATER DAMAGE/INFILTRATION	TS	TROUBLESHOOT	R1
4665672	3669	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.50	04/13/2014					IN	INSPECTED	R1
	5096	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/13/2014					IN	INSPECTED	R1
4665677	3340	E			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			1.00	04/08/2014					IN	INSPECTED	R1
	4924	G			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.50	04/07/2014					IN	INSPECTED	R1
4665796	5091	A			S52	CCTV DATA PACK/EVENT RECORDER	ZLV	CCTV EQUIPMENT		'A' CAR	2.00	03/31/2014	COUPLED TO A TYPE-1 W/NO CCTV	OVERAMPLIFICATION CAUSED A REAR IMAGE TO BE STATIC/BLACK ITS NOT SUPPOSED TO HAVE A REAR IMAGE ON A SINGLE HOWEVERSTATIC WAS MESSING UP FRONT VIEW,ADJUSTED CCTV AND R/R CONTROL BOX RX	05	BROKEN	RR	REMOVED AND REPLACED	R1
4669434	4154	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER			0.75	04/15/2014					IN	INSPECTED	R1
		B			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST			0.75	04/15/2014					IN	INSPECTED	R1

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~

RO	Badge	Sub Repair Order	Group Class	Equip Comp Num	Symp Code	Symptom Code Description	Comp Code	Component Type	Location Name	Location Description	Rep Hours	Date Completion	Description	Description Extended	Defect Code	Defect	Action Code	Action	Shop
4670190	3661	A			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	04/17/2014					IN	INSPECTED	R1
	4120	B			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	04/17/2014					IN	INSPECTED	R1
4670739	4096	G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	04/24/2014					IN	INSPECTED	R1
	5094	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	04/17/2014					IN	INSPECTED	R1
4670741	1209	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	1.00	04/17/2014					IN	INSPECTED	R1
	4120	A			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.75	04/15/2014					IN	INSPECTED	R1
4671185	3749	A			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	04/23/2014					IN	INSPECTED	R1
4671348	3583	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LVFE	CAMERA, EXTERIOR	.	.	0.75	04/06/2014	CHECKED BOTH LEFT AND RIGHT	MONITORS FOUND BOTH THE SAME	86	SUSPECTED FAILURE	CK	CHECKED	R1
4671447	5098	A			N04	T-1 PM 40,500 MILE PKG	MI312	TEST: CCTV	.	.	0.50	04/20/2014					IN	INSPECTED	R1
4671670	3749	C			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	04/15/2014					IN	INSPECTED	R1
		E			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	04/15/2014					IN	INSPECTED	
4672125	4154	A			SS1	UNSCHEDULED SYSTEM INSPECTION	2LV	CCTV EQUIPMENT	.	.	0.50	04/07/2014	222 IS COUPLED TO A TYPE 3	WITH OUT SIDE CAMERAS	86	SUSPECTED FAILURE	CK	CHECKED	R1
4672238	3632	B			N24	T-3 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	1.00	04/23/2014					IN	INSPECTED	R1
		D			N24	T-3 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	04/23/2014					IN	INSPECTED	
4674032	4095	B			SS2	CCTV DATA PACK/EVENT RECORDER	4LVH	RX UNIT	.	.	0.50	04/09/2014	R/R RECEIVER		27	DEFECTIVE	RR	REMOVED AND REPLACED	R1
4674738	3661	E			N14	T-2 PM 40,500 MILE PKG	MIL197	EVENT RECORDER	.	.	0.50	04/22/2014					IN	INSPECTED	R1
		G			N14	T-2 PM 40,500 MILE PKG	MIL211	CCTV TEST	.	.	0.50	04/22/2014					IN	INSPECTED	
4675666	3749	C			N30	T-4 PM 9,000 MILE PKG	4LV	CCTV EQUIPMENT	.	.	5.00	04/16/2014	T/S CAMERA 3 PROBLEM VERIFIED	IMAGE STRAIGHT FROM CAMERA GOOD, TROUBLE SHOOTED PROBLEM WENT AWAY, POSSIBLE LOOSE CONNECTION, WORKING NORMAL NOW	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4677150	4157	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	0.50	04/16/2014	DVR OPERATION WORKING OK NO	FAULTS	86	SUSPECTED FAILURE	CK	CHECKED	R1
4677155	4921	A			S23	CCTV/APC/EVENT RECORDER FAILS	222000	CCTV EQUIPMENT	.	'B' CAR	2.00	04/16/2014	THIS MONITOR WAS NOT "FREEZING	UP" WHEN DOORS OPEN BUT IN THE PROCESS I DISCOVERED THERE WAS NO REAR VIEW UPON RELEASE ON EITHER MONITOR CHECKED THE OTHER CAR (231) & FND THE SAME PROBLEM UNCOUPLED & BOTH CARS WORK NORMALLY WHEN SINGLE CLEANED ELECTRICAL HEAD & RECOUPLED & PROBLEM PERSISTS. THERE IS A TRAINLINE PROBLEM THAT WAS NOT FOUND NEEDS FURTHER T/S	61	MALFUNCTION/REASON UNKNOWN	TS	TROUBLESHOOT	R1
4677537	4147	A			S23	CCTV/APC/EVENT RECORDER FAILS	4LV	CCTV EQUIPMENT	.	.	0.50	04/17/2014	T/S DARK MONITOR, WORKING FINE		86	SUSPECTED FAILURE	TT	TESTED	R1
4680229	4095	A			S07	CAB ELECTRIC CONTROLS	2LV	CCTV EQUIPMENT	.	.	1.00	04/23/2014	CHECK SETTINGS ON DVR/EVERY	THING OK ALL CAMERAS WORK	61	MALFUNCTION/REASON UNKNOWN	ND	NO DEFECT FOUND	R1

~~SENSITIVE SECURITY INFORMATION~~

Tri-County Metropolitan Transit District

May 14, 2014

If this document/information is found, please deliver to appropriate department or position as soon as possible.

~~Warning: This record contains Sensitive Security Information that is controlled under 49 CFR parts 15 and 1520. No part of this record may be disclosed to persons without a "need to know", as defined in 49 CFR parts 15 and 1520, except with the written permission of the Administrator of the Transportation Security Administration or the Secretary of Transportation. Unauthorized release may result in civil penalty or other action. For U.S. government agencies, public disclosure is governed by 5 U.S.C. 552 and 49 CFR parts 15 and 1520.~~